


CPU Holder Fix Slide Rotate




Before assembly

Please spend some times to read this and follow the procedures step by step.


Some panels are viewed differently from the exploded drawing below. This is for extra clarity.
Do not discard any of the packaging until you have checked all the parts and the package of fittings. If you are missing any of the parts, please contact the store from which you purchased your products. The staff will do their best to help you.

Parts Check-List

01 Slide Support




02 Beltlock



Note: As an option when needs are for lower position 65mm.

Please order Codeno 427-CS08 LiftConsole Click-System.



Caution:

Regular cleaning with a clean dry cloth is usually sufficient, but for stubborn marks, wipe over gently with a clean damp cloth. Never use strong detergents or abrasive cleaners as these may damage the surface finish of your furniture. There are many small components used in the construction of this unit. These loose items should be kept away from young children while assembling your unit.

Patent Pending

Fitting Check-List

03 Screw




X6

04 Stopper






X4


Note: As an option when needs are for lower position 100mm. Please order Codeno 427-CS09 LiftConsole Click-System.



www.bakkerelkhuizen.com



The rope pierces through the front of the beltlock (as figure a. arrow) and strings as a circle. Putting the rope on top of the plate (as the figure b. location). Then putting the CPU on with care.





Adjust the length of the rope for CPU, the method as following :

1. Pull down one of the rope first and then another rope.
2. Repeat step 1, until the top of the CPU touches the stoppers.
3. Press down the beltlock cover (see figure right) in order to fit the CPU properly and avoid the rope loose.
4. Piercing through the top of the hoop of the beltlock with the remaining rope and the rope won't hang down to the ground. (see figure right)




Note :

- * Do not move over-high when supporting a CPU.
- * Supporting the CPU during the whole adjustment.




Note:

- * Make sure the spring set up on the pin.
- * Set up pin in slide in order to prevention the revolver set take off.




CPU Holder Fix Slide Rotate



Tack för att Ni valt en produkt från Kondator
Ägna gärna några minuter att läsa denna monteringsanvisning.
Detta är ett steg för steg underlättar monteringen.
Bifogat finns en lista på de tillbehör som skall finnas med i paketet. Kontrollera noga innehållet före montering !

Innehåll

01 CPU-Hållare & skena



X1


02 Spännsband



X2

ATT NOTERA: Vid behov kan LiftFlex kompletteras med distanser 100mm höjd. Vänligen beställ Artnr 427-CS09

LiftConsole med click-system.



Artnr 427-CS27

Rekommendationer:

Rengör regelbundet med en ren trasa.

Använd aldrig starka lösningsmedel.

Övriga detaljer

03 Skruv X6



X6


04 Friktonsbelägg X4






X4

ATT NOTERA: Vid behov kan LiftFlex kompletteras med distanser 100mm höjd. Vänligen beställ Artnr 427-CS09

LiftConsole med click-system.





www.bakkerelkhuizen.com




Lösgör sprintlåset och drag ut släden från skenan. Fäst skenan på lämplig plats undet bordet med bif skruv (03).

Dra igenom spännsband (02) i lös-spännet (enl pilen riktning, fig a) så att öglor erhålls. Häng upp resp öglor enl (fig b) i upphängningsbleckens (01) krokar. För därefter in datorn försiktigt i öglorna.



Anvisningar för justering av spännsbanden:


1. Drag åt båda spännsbanden (02)
2. Upprepa enl ovan tills datorn ovansida ligger stadigt mot friktionsbelägen/upphängningsblecken.
3. Justera och stoppa in "överbiljet spännsband" i där avsedd ring.
4. Pressa därefter ned spännet på låset. Detta säkerställer datorns position i spännsbanden.



Kontrollera att fjädern till låssprinten finns på plats.




Skjut in släde med fastspänd dator i monterad slädkon under bordet




b.

För in låssprintens långa tapp (A) med fjäder i skenans sidohål. Pressa in tappen, samt för därefter in låssprintens kortare tapp (B) i motstående sidohål.



5



6

Patent Pending