Assembly Instructions



bouncepad[™]

What's in the Box



What's in the Box



Faceplate x1



Tools for the Job



Recommended Installation Height





Through Mount

Step 1 of 4 Mark the Drill Holes





Scale 1:1

Drill the Holes

13/64"

Through Mount

Step 3 of 4 Screw in socket setscrews by hand





IMPORTANT: Line up the screws as shown (left)



Surface Mount



Surface Mount

Step 2 of 4 Drill the Holes

This diagram can be used as a drill template



NOTE: The I6mm / 41/64" hole is not required if attaching to surface with no access beneath as the power cable can be routed along the surface

11.

Surface Mount

Step 3 of 4 Attach mount plate

 Screw Mount plate onto Stalk
OPTIONAL Route power cable down the Stalk and through cable channel (only applicable if you choose to route cable along surface)









Route Cable





15.







Your Bouncepad is now installed

For further information and support please contact us:

UK & International

Deutschland

+44 (0) 020 3693 0000 hello@bouncepad.com www.bouncepad.com +49 (0) 30 6098 5170 hallo@bouncepad.com www.bouncepad.com/de

USA & Canada

1-617-804-0110 hi@bouncepad.com www.bouncepad.com/us

Contact Details

UK & International

+44 (0) 020 3693 0000 hello@bouncepad.com www.bouncepad.com

Deutschland

+49 (0) 30 6098 5170 hallo@bouncepad.com www.bouncepad.com/de

USA & Canada

1-617-804-0110 hi@bouncepad.com www.bouncepad.com/us

