

Release notes and update instructions

AV Bridge 2x1 Presentation Switcher

Current Release

AV Bridge 2x1 1.4.0

March 27, 2026

New Features

- Added support for SpeakerVIEW Controller.
- Added support for SpeakerVIEW Controller.
- Added customizable UI.
- Added CLISH 'info' command to query product and room label information.
- Added support for 256 camera presets via CLISH.
- Added support for removing the password requirement when logging in over telnet and RS-232.

Improvements

- Improved USB enumeration behavior.
- Changed HID controls flag to be separate controls for gain and mute.
- Fixed a bug that caused a macro execution to hang if it included 'monitor buttons'.
- Fixed a bug that caused data to not migrate properly when updating from a previous release.
- Fixed a bug that caused passwords with a colon in them to not work properly:
- Fixed a bug that caused some audio settings to not work properly.
- Fixed a bug that caused the device to lock up when migrating audio configs.
- Fixed an issue that could cause data loss in certain circumstances.
- Fixed CLISH hint and range for chained preset recall.
- Improved graphics import and deletion in the web UI.
- Moved focus related UVC controls to the "CCU" category instead of the "PTZ" category.
- Removed Identification Signal Enabled banner from web UI.
- Various cosmetic improvements to the web UI.
- Various infrastructure updates.
- Enable NTP by default on Xyte-enabled devices.
- Fixed slow hostname validation that caused noticeable UI freezing.
- User Interface - Keyer settings "Show Select Key Source Button" disable no longer removes the Source Button.
- Fixed Telnet command "graphics source get".
- Removed Telnet - "video" commands with duplicate functions.
- Fixed a bug that caused certain network configurations to not work properly.

Release History

AV Bridge 2x1 1.3.1

November 1, 2023

Improvements

- Manufacturing improvements.

AV Bridge 2x1 1.3.0

October 12, 2023

New Features

- The Streaming page now includes a button to copy the streaming URL to the clipboard.
- You can now control the on-screen IP and MAC address display from the System page of the web

interface. The Device Utilities area on the Firmware tab provides a Data Screen button that shows the current state of the display.

- When not using this device for the USB stream's audio, you can now disable the USB Audio Enumeration setting on the Streaming page.
- You can now send Command Line Interface SHell (CLISH) commands using SSH as a secure alternative to Telnet. SSH access is disabled by default, and can be enabled on the device's Security page.
- The web interface now provides six factory audio configurations, and can store up to 16 custom audio configurations.
- The command `audio config {recall {factory <1 - 6> | custom <1 - 16>} | store custom <1 - 16>}` recalls the specified factory or custom audio configuration, or stores a custom audio configuration.
- The command `video pip swap` exchanges the PIP for the main image.
- The command `audio speechlift { on | off | set { input } }` provides Speech Lift functionality, sending microphone audio to room speakers.

Improvements

- RTMP streaming settings now allow more streaming services to be added.
- Parametric equalizer (PEQ) filter settings are now available on all four Dante audio inputs.
- UVC extensions for pan/tilt/zoom/focus and for color/lighting adjustments can now be enabled separately.
- Updating firmware or importing a configuration no longer resets the Chairman Override Input to Line/Mic 1.
- Occasionally the device would stop being available to the connected computer. This has been fixed.
- Using UVC controls to move a paired ePTZ camera could produce unexpected results. This has been fixed.
- Importing a configuration file or reinstalling firmware no longer resets UVC extension enablement.

AV Bridge 2x1 1.2.2

June 10, 2022

New Features

- The option to automatically go to standby mode is now available in the web interface. (System page, General tab)

Improvements

- Importing a configuration did not restore audio settings correctly. This has been fixed.
- Various audio settings could revert to factory default values during a firmware update. This has been fixed.
- When set to go to standby on USB disconnect and connected to a USB extender, the device now correctly enters standby.
- Improved USB playback quality.

AV Bridge 2x1 1.2.1

October 6, 2021

Improvements

- The device can now process USB audio commands while in standby.
- Camera standby setting moved to System > General tab.
- RTMPS streaming has been fixed.
- Camera settings persistence improved across power cycles.

AV Bridge 2x1 1.2.0

August 9, 2021

Improvements

- At low streaming resolutions and frame rate, video distortion could be present. This has been fixed.
- Far-end (UVC) control of a connected camera did not always work properly if the camera's Image Flip mode was selected. This has been fixed.
- In some cases, connecting the USB port to an Apple® macOS® device while the AV Bridge 2x1 was on resulted in audio distortion. This has been fixed.
- On DHCP-enabled devices, it was possible to have more than one gateway address listed. This has been fixed.

AV Bridge 2x1 1.1.1

November 6, 2020

Improvements

- Improved USB enumeration behavior.
- Video artifacts could appear when receiving HDMI video from a OneLINK system. This has been fixed.

AV Bridge 2x1 1.1.0

August 29, 2020

New Features

- We have placed the company's standard privacy notice on this product's Help page. This product does not record or save audio or video files, and it does not store any identifying information other than what you may choose to enter on the Room Labels page of the web interface. However, the device's IP address is considered "personally identifiable information" for the purposes of the privacy notice. This information is stored for display to the user, but not otherwise shared or transmitted.
- Added graphics management commands to the serial API:
 - The command `graphics enable { get | on | off | toggle }` returns or sets the state of the graphics capability.
 - The command `graphics source { get | set <image_filename> | clear }` specifies the graphics file to use.

Improvements

- Improved color accuracy on video outputs.
- Enhanced compatibility with the new Vaddio Device Controller.
- Improved USB enumeration behavior.
- Improved video quality for lower-resolution USB streams.
- Corrected an issue that could potentially cause the Discover Devices button not to work.
- When changing the selected video input, the HDMI output could flicker if the PIP was on. This has been fixed.
- Under certain circumstances, the video transition type could change unexpectedly. This has been fixed.
- Changing to a different video input could result in USB re-enumeration when UVC extensions are disabled. This has been fixed.
- HDMI output was not always displayed at the correct aspect ratio when using resolutions with aspect ratios of other than 16:9. This has been fixed.

- Volume sliders and meters for audio outputs did not always interact as expected. This has been fixed.
- Occasionally, echo cancellation stopped working after the device was rebooted, and had to be toggled to be restarted. This has been fixed.

AV Bridge 2x1 1.0.0

March 17, 2020

Notes

- Initial release.
- The video output may flicker when swapping inputs while the PIP is active.
- The video aspect ratio may not always be maintained when using different output resolutions.


Firmware Update Instructions – AV Bridge 2x1

The process for updating firmware is the same for virtually all Vaddio products. *Your device's web interface may display different information from the screen shot in this procedure.*

Caution

The device must remain connected to power and to the network during the update. Interrupting the update could make the device unusable. If the update does not run, DO NOT DISCONNECT POWER. Call Vaddio Tech Support immediately: +1 763-971-4400 or 800-572-2011.

1. Download the firmware file if you have not done so already.
2. Access the device's web interface and log in as `admin`.
3. On the System page, select Choose File and select the file you downloaded. Then select Begin Firmware Update.



4. Read the Confirm dialog box, then select Continue. You will be prompted to log in again when the process is complete.

This update can take up to 5 minutes to complete. While you're waiting, you could try the following:

- Make a list of ways to improve your least favorite vegetables. Extinction might be an option.
- Decide which animal would be the least believable star of a monster movie.
- Think of three colors that should appear more in nature.

After the update is complete, the System page will display the new firmware version under System Information. Enjoy that new-firmware smell!

Vaddio is a brand of Legrand AV Inc. · www.legrandav.com · Phone 800.572.2011 / +1.763.971.4400 · Email – Europe, Middle East, Africa: av.emea.vaddio.support@legrand.com | All other regions: av.vaddio.techsupport@legrand.com

Vaddio is a registered trademark of Legrand AV Inc. All other brand names or marks are used for identification purposes and are trademarks of their respective owners. All patents are protected under existing designations. Other patents pending.

©2026 Legrand AV Inc.

A brand of  **legrand**