Windows 10 IoT Enterprise LTSB 2016 for Dell Wyse 5070 Thin Client

Release Notes



Contents

| Chapter 1: | |
|----------------------------------|----|
| - Release type and definition | |
| Release type and definition | |
| What's new | 4 |
| Supported features | |
| Hardware capability | |
| Fixed issue | 14 |
| Known issues | 14 |
| Supported peripherals | |
| Used and free space details | |
| Operating system components | |
| QFEs | |
| | |
| | |



Release type and definition

Software releases are created to correct defects, make enhancements, or add new features. These releases are tested on all current, actively shipping platforms and operating systems, as applicable. This release notes contain details on the supported platforms, any changes in the configuration settings and licensing details as well. The bug fixes along with the workarounds are documented in the release notes. Any changes in the feature functionality from an end-user perspective are listed with the description of each feature at a high level.

Release type and definition

This release note contains information for Windows 10 Enterprise 2016 LTSB, also known as Redstone 1 (RS1) on Wyse 5070 Thin Client.

Table 1. Release detail and specification

| Release detail | Specification | |
|------------------------------------|--|--|
| Platform | Wyse 5070 thin client | |
| Operating system | Windows 10 Enterprise 2016 LTSB | |
| Previous product version | 10.03.06.10.18.00 | |
| Current product version | 10.03.06.03.19.00 | |
| Build version | 10.03 | |
| System type | 64-bit operating system | |
| Supported languages | • English—en-US | |
| | • German—de-DE | |
| | French France—fr-FR | |
| | French Canada—fr-CA | |
| | • Italian—it-IT | |
| | • Spanish—es-ES | |
| | • Japanese—ja-JP | |
| | • Korean—ko-KR | |
| | Chinese Simplified—zh-CN | |
| | Chinese traditional—zh-TW | |
| | Brazilian Portuguese—pt-BR | |
| Supported USB Imaging tool version | 3.1.0 | |
| Wyse Management Suite package Name | WIN10_5070_March2019.exe | |
| Build size | 10.4 GB (11,269,474,427 bytes) | |
| BIOS version | 1.1.4 | |

CAUTION: Please follow proper write filter and Windows Page File usage instructions at all times. Such instructions include making sure that the write filter is enabled during regular use and is disabled only

temporarily by an administrator when required for image upgrades, applying security patches, registry changes and application installation. The write filter should be re-enabled as soon as such tasks are completed. Such instructions further include never enabling the Windows Page File feature during regular use of the thin client. Any operation of a Dell Wyse Windows Embedded Thin Client with the write filter turned off during regular use and/or with the Windows Page file enabled will prematurely wear out your Flash/SSD storage, decrease performance and decrease the lifespan of the product. Dell is not responsible for, and will not, warrant, support, repair or replace any thin client device or component that fails to operate properly due to a failure to follow these instructions.

What's new

New and enhanced features in build 10.03.06.03.19.00

- Apacer Solid-State Drives registry settings are updated.
- Application Launch Manager is updated to version 1.0.0.2.
- QFEs are updated until October 2018.

New and enhanced features in build 10.03.06.10.18.00

- The component Computrace version 8.0.944 by Absolute Software Inc is removed.
- CAD_MAP_VDI is updated to version 1.0.0.1.
- Wyse Device Agent is updated to version 14.2.0.51.
- ThinPrint Viewture is updated to version 11.22.2.3.
- Microsoft Visual C++ 2008 Redistributable x64 9.0.30729.6161 is supported.
- Citrix Receiver is updated to version 14.11.0.17061.
- Citrix HDX RealTime Media Engine is updated to version 2.4.0.1233.
- VMware Horizon Client is updated to version 4.8.0.1562.

Supported features

The following features are supported in this release:

Threat Defense

Dell Data Protection | Threat Defense Agent (powered by Cylance) detects and blocks malware before it can affect your computer. Cylance uses a mathematical approach for malware identification. It uses machine learning techniques instead of reactive signatures, trust-based systems, or sandboxes. Dell Data Protection | Threat Defense analyzes potential file executions for malware in the operating system.

Connection brokers

- VMware Horizon client is updated to version 4.8.0.1562.
- Citrix Receiver is updated to version 14.11.0.17061.
- Ericom WebConnect is updated to version 7.5.1.

Out-of-Box driver install

All the respective device drivers are pre-installed in the operating system.

Dell wallpapers

Older wallpapers and themes are replaced with the new Dell wallpapers and themes.

XML driven PowerShell scripts

Customization scripts are ported to the PowerShell scripts, and are based on the XML file input.

Log files for customization

A log file is created for the customization scripts where you can view the overall script execution.

User accounts

You can log in as an administrator or as a standard user.

The following are the login credentials for user and administrator accounts:

Table 2. Login credentials

| Account detail | Password |
|------------------------|------------|
| User | DellCCCvdi |
| Admin | DellCCCvdi |
| TightVNC—Administrator | DELL |
| BIOS—Administrator | Fireport |

Flash.sys

Hostname calculation allows you to enable and disable the Hostname calculation in flash.sys.

The following are the features of Hostname calculation:

- You can disable or enable the Hostname calculation.
- You must ensure that altering the MAC ID for a client does not perform a Hostname calculation.
- If you require a Hostname calculation to perform after a change in MAC ID (NIC card change), then you must use the MINWITHNET option.

Event Viewer log preservation

Event Viewer log preservation feature allows you to enable or disable Event Viewer log saving when the File Based Write Filter (FBWF) is on. This feature enables you to collect event logs if they are required for debugging or analysis purposes.

Dell Thin Client Application

Dell Thin Client Application is a replaced for Client Information Application with a new User Interface (UI). You can view and configure thin client device, system shortcuts, custom fields, RAM disk, autologon, and CAD map.

(i) NOTE: By default, RAM disk size is 512 MB for thin clients with 8 GB RAM.

Internet Explorer 11

- **Performance enhancements**—Microsoft has included support for web standards like CSS animations, HTML5 spell checking, and improved JavaScript performance.
- Security enhancements—The main security addition to Internet Explorer 11 is Enhanced Protected Mode, which locks down parts of the Windows operating system, preventing the browser from accessing the operating system.

The following Internet Explorer 11 features are customized by default:

• First run customizations are disabled.

- Internet Explorer 11 enhanced protection mode is enabled.
- Internet Explorer cookies and cache are redirected to z: RAM Disk.
- Cache content is limited to 100 MB.
- Browsing history is cleared when you exit Internet Explorer.

USB redirection

USB redirection is applicable for all users of the client machine with all the published XenDesktop irrespective of the setting **Simplify device connections for me** in the XenDesktop connection preferences user interface.

ENERGY STAR specification

Windows 10 IoT Enterprise on Wyse 5070 thin client is ENERGY STAR version 6.0 compliant.

The following are the details in the Control Panel applet for power options:

- Supports Wake on LAN (WoL) during power off.
- Supports Idle state wake up from the sleep mode.
- Screen off timer is 10 minutes.
- Sleep timer is 15 minutes.

Microsoft SCCM 2016 server information

System Center Configuration Manager (SCCM) is supported for standard deployment of images.

BIOS details

Wyse 5070 thin client supports Dell BIOS and Wyse BIOS entries. The BIOS image is included in the latest Wyse Management Suite release.

Keyboard filters

You can use keyboard filters to disable key presses or combinations. For example, you can disable common Windows key combinations such as Ctrl+Alt+Delete and Alt+Tab. You can disable any key or key combination.

Windows Defender Advanced Threat Protection

Windows Defender Advanced Threat Protection feature helps enterprises to detect, investigate, and respond to advanced attacks on their networks.

C-A-D tool

The C-A-D tool allows administrators to map the Ctrl+Alt+Del key combination of VDI applications to display the Ctrl+Alt+Del screen of the VDI application. If the C-A-D tool is enabled, you can use Ctrl+Alt+Del key combination for all VDI applications.

(i) NOTE: By default, the C-A-D tool is enabled.

Sysprep using User Interface

The System Preparation tool (Sysprep) can now be configured using the inbuilt user interface. Using this tool the data gets cleared from the system and the system can be customized as per the requirement. The operating system will be like a new installation.

The Sysprep tool is used with other deployment tools to install the Microsoft Windows operating systems with minimal intervention by an administrator.

Buildmaster.cmd is the main program that calls other executable files that prepares the thin client for the Windows installation.

Buildmaster.cmd is located in the<drive C>\Windows\Setup on all installations.

 $\label{eq:Sysprep} Sysprep must always be run from the <drive C>\Windows\Setup and must run on the version of Windows with which it was installed.$

The Sysprep tool contains the following two options:

- Custom Sysprep, see Running the Custom Sysprep tool.
- Config Sysprep, see Running the Config Sysprep tool.

Prerequisites

The following are the pre-requisites to run the Custom Sysprep tool:

- Unified Write Filter must be in disable state.
- Logging framework must be available on your thin client.
- Power Shell script execution environment must be available.
- Custom Sysprep and Configuration Sysprep (SCCM) scripts must be available.
- Host Name calculation feature must be available.
- If the flash size or HDD size is more than 32 GB, reduce it to less than 32 GB for a better custom sysprep process.

NOTE: You cannot access the thin client if you terminate the Sysprep process. Make sure that the device is ready before you use the Sysprep tool.

CAUTION: After you run the Sysprep tool, enable the Unified Write Filter to ensure device security.

Running Custom Sysprep tool

- Disable File based Write Filter.
- Logging framework must be available on your thin client.
- PowerShell script execution environment, Custom Sysprep, Configuration Sysprep (SCCM) scripts, and Hostname calculation feature must be available.
- Reduce the flash drive or hard drive size to less than 32 GB.

To run the Custom Sysprep tool, do the following:

- 1. Go to <drive C>\Windows\Setup.
- Right-click Build_Master.cmd, and select Run as administrator. The Config Master window is displayed.

| Config Master | | = 0 X |
|---------------|---|-------|
| | | |
| | \frown | |
| | DELL | |
| | | |
| | \smile | |
| | Prefixquiaite check completed, Please click on Next to continue configuring the Device. | |
| | Write Filter is Disabiled or not present V | |
| | Logging Framework is present V PSexecution environment is present V | |
| | Custom and SCCM configuration stages available/ | |
| | | |
| | NEXT CANCEL | |
| | Weav Error log | |
| | | |
| | | |

Figure 1. Config Master

3. Click Next.

The **Configuration** screen is displayed.

| Configurations | | | | |
|-------------------|-------------------|----------------------|---------------------|------------------|
| Custom co | nfiguration | O SCCM configuration | on | |
| Host Name calcu | lation | | | |
| Enable | O Disable | O Retain current | settings | |
| Configure Domai | in options | | | |
| User Name: | Test | |] | |
| | | | | |
| Password : | ••••• | | | |
| Domain : | Test.com | |] | |
| | | | 1 | |
| OU : | | | Configure OU option | Save Credentials |
| Configure local a | ccount credentia | ls | | |
| ✓ Enable loc | cal account crede | ential changes | | |
| | | | | |
| | | | Next | Cancel |

Figure 2. Configuration

- 4. Select Custom configuration in the Configurations section.
- 5. Enable or disable hostname calculation in the Host Name calculation section.
- 6. Enter the appropriate values in the **Configure Domain options** section, and click **Save Credentials**.
- 7. Click **OK** when prompted.
- 8. Select Enable local account credentials changes.

The changes that are made to the credentials are applied.

9. Click Next.

The Credential Manager page is displayed.

| Administrator User | User Name: | Administrator |
|-----------------------|-----------------------|---------------|
| | Enter New Password: | ••••• |
| | Confirm New Password: | ••••• |
| | | Save |
| | | |
| | | |
| | | |
| | Ар | ply Cancel |

Figure 3. Credential Manager

- 10. Select the user account, and type the login credentials.
- 11. Click Save.
- 12. Click **Apply** to save the changes.
 - This process takes 5–10 minutes to complete. The device turns off after the Sysprep process is complete.
 - () NOTE: You cannot access the thin client if you terminate the Sysprep process. Make sure that the device is ready before you use the Sysprep tool.

Running the Config Sysprep tool

To run the Config Sysprep tool, do the following:

- 1. Go to <drive C>\Windows\Setup.
- 2. Right-click Build_Master.cmd, and select Run as administrator. The Config Master window is displayed.

| ල Config Mather | | - 0 |
|-----------------|---|-----|
| | \bigcirc | |
| | (Dell) | |
| | Preflequisits check completed, Please click on Next to continue configuring the Device. | |
| | Write Filter is Disabled or not present 🗸 | |
| | Logging Framework is present 🗸 | |
| | PSexecution environment is present | |
| | | |
| | NEXT CANCEL View Enter log | |
| | | |
| | | |

Figure 4. Config Master

3. Click Next.

The **Configuration** screen is displayed.

| O Custom cor | nfiguration | SCCM configuration | on | |
|------------------|------------------|--------------------|---------------------|-----------------|
| lost Name calcul | ation | | | |
| Enable | O Disable | ○ Retain current | settings | |
| Configure Domai | n options | | | |
| User Name: | | | | |
| Password : | | | | |
| | | | | |
| Domain : | | | | |
| OU : | | | Configure OU option | Save Credential |
| onfigure local a | ccount credentia | ls | 4 | |
| Enable loc | al account crede | ntial changes | | |

Figure 5. Configuration

- 4. In the Configurations section, select SCCM configuration.
- 5. In the Host Name calculation section, enable or disable hostname calculation.

(i) NOTE: The Configure Domain Option and Configure local account credentials field are grayed out.

- 6. Click Apply to save the changes.
- After the completion of SCCM Config Sysprep, the HAgent service ends. You can now perform the pull operation using SCCM.

Hardware support information

- Rich 4K display capability is provided.
- Option for 802.11 a/b/g/n/ac wireless is provided.
- Intel Celeron® J4105 CPU at 1.50 GHz (Economy configuration), Intel Pentium® Silver J5005 at 1.50 GHz (Standard and Extended configuration) is supported.
- Video adapters—DP to DVI, DP to VGA—is supported.
- Dynamic throttling for higher performance is supported.

Hardware capability

Display settings for Wyse 5070 thin client

By default, the Display Settings UI is available in both user mode and admin mode. Any changes to display preferences made through this UI is saved for the user.

Table 3. Port preferences

| Wyse 5070 thin client with Celeron processor | Optional port can be used as second RJ-45, SFP, VGA, or second serial port. If wireless is enabled, the optional port cannot be used as second RJ-45 or SFP. When monitor is connected on USB-C port, DisplayPort 2 becomes inactive. |
|--|--|
| Wyse 5070 thin client with Pentium processor | Optional port can be used as second RJ-45, SFP, VGA, or second serial port. If wireless is enabled, the optional port cannot be used as second RJ-45 or SFP. Back headset is disabled if front headphone is used. When monitor is connected on USB-C port, DisplayPort 2 becomes inactive. When the VGA monitor is present on VGA optional port, DisplayPort 3 becomes inactive. |
| Wyse 5070 Extended thin client | Optional port can be used as second RJ-45, SFP, or VGA. If wireless is enabled, the optional port cannot be used as second RJ-45 or SFP. Back headset is disabled if front headphone is used. When monitor is connected on USB-C port, DisplayPort 2 becomes inactive. When the VGA monitor is connected on VGA optional port, DisplayPort 3 becomes inactive. Power option is available on the first serial port. PCle slot is available. |

Wyse 5070 thin client with Celeron processor

Table 4. Wyse 5070 thin client with Celeron processor

| Number of Displays | Supported display resolution | | |
|--------------------|--|------------------|--|
| | 4K resolution ¹ Non- 4K resolution ² | | |
| One display | Yes | Yes | |
| Two displays | Yes | Yes | |
| Three displays | No ³ | Yes ³ | |

1. 4K resolution—3840 x 2160 @ 60 Hz

2. Non-4K resolution—Up to 2560 x 1600 @ 60 Hz

3. VGA port does not support 4K display. However, it supports a display with 1080p screen resolution.

Table 5. Ports

Table 5. Ports

| Ports | DP1 | DP2 | VGA | USB Type-C |
|-----------------------|-----|-----------------|------------------|-----------------|
| Monitor priority | 1 | 2B ² | 3 | 2A ² |
| 4K display resolution | Yes | Yes | No ¹ | Yes |
| Non-4K resolution | Yes | Yes | Yes ¹ | Yes |

1. VGA port does not support 4K display. However, it supports a display with 1080p screen resolution.

2. DP2 and USB Type-C port are mutually exclusive with USB Type-C port taking higher priority.

Wyse 5070 thin client with Pentium processor

Table 6. Wyse 5070 thin client with Pentium processor

| Number of Displays | Supported display resolution | | |
|--------------------|--|-----|--|
| | 4K resolution ¹ Non- 4K resolution ² | | |
| One display | Yes | Yes | |
| Two displays | Yes | Yes | |
| Three displays | No ³ | Yes | |

1. 4K resolution—3840 x 2160 @ 60 Hz

2. Non-4Kresolution—Up to 2560 x 1600 @ 60 Hz

3. If you connect three displays, two monitors will have 4K resolution and one monitor will have 2560 x 1600 @ 60 Hz.

Table 7. Ports

| Ports | DP1 | DP2 | DP3 | VGA | USB Type-C |
|--------------------------|-----|-----------------|-----------------|-----------------|-----------------|
| Monitor priority | 1 | 2B ² | 3B ³ | 3A ³ | 2A ² |
| 4K display resolution | Yes | Yes | Yes | No ¹ | Yes |
| Non-4K resolution | Yes | Yes | Yes | Yes | Yes |

1. VGA port does not support 4K display. However, it supports a display with 1080p screen resolution.

2. DP2 and USB Type-C port are mutually exclusive with USB Type-C port taking higher priority.

3. DP3 and VGA port are mutually exclusive with VGA port taking higher priority.

Wyse 5070 Extended thin client with AMD GPU

Table 8. Wyse 5070 Extended thin client with AMD GPU

| Number of Displays | Supported display resolution | | | |
|--------------------|--|-----|--|--|
| | 4K resolution ¹ Non- 4K resolution ² | | | |
| One display | Yes | Yes | | |
| Two displays | Yes | Yes | | |

| Number of Displays | Supported display resolution | | |
|-----------------------------|------------------------------|-----|--|
| Three displays ⁴ | Yes | Yes | |
| Four displays ⁵ | Yes | Yes | |
| Five displays | No ³ | Yes | |
| Six displays | No ³ | Yes | |

Table 8. Wyse 5070 Extended thin client with AMD GPU

1. 4K resolution—3840 x 2160 @ 60 Hz

- 2. Non-4K resolution—Up to 2560 x 1600 @ 60Hz Support only up to four monitors with 4K screen resolution @60 Hz.
- **3.** If you connect five or six displays, four monitors will have 4K resolution and other monitors will have a maximum resolution of 2560 x 1600 @ 60 Hz.
- **4.** For three displays, Dell recommends that you configure first two 4K displays on the main board (DP1~DP3), and the third 4K display on AMD GPU card.
- 5. For four displays, Dell recommends that you configure first two 4K displays on the main board (DP1~DP3), and the remaining two 4K displays on AMD GPU card.




Figure 6. Ports of Wyse 5070 Extended thin client

Table 9. Ports

Table 9. Ports

| Ports | DP1 | DP2 | DP3 | VGA | USB-C | mDP4 ³ | mDP5 ⁴ | DP6 ⁵ |
|-----------------------|-----|-----------------|-----------------|------------------|-----------------|-------------------|-------------------|------------------|
| Monitor priority | 1 | 2B ⁶ | 3B ⁷ | 3A ⁷ | 2A ⁶ | 4 | 5 | 6 |
| 4K display resolution | Yes | Yes | Yes | No ¹ | Yes | Yes | Yes | Yes |
| Non-4K resolution | Yes | Yes | Yes | Yes ² | Yes | Yes | Yes | Yes |

1. VGA port does not support 4K display. However, it supports a display with 1080p screen resolution.

- 2. VGA port supports 1080p screen resolution.
- 3. mDP4 port refers to the top mDP port of the AMD GPU slot.
- 4. mDP5 port refers to the middle mDP port of the AMD GPU slot.
- 5. DP6 refers to the bottom DP port of the AMD GPU slot.
- 6. DP2 and USB Type-C port are mutually exclusive with USB Type-C port taking higher priority.
- 7. DP3 and VGA port are mutually exclusive with VGA port taking higher priority.

Monitor priority—The following order defines the monitor priority set on Windows 10 IoT Enterprise for Wyse 5070 thin client:

- DP1 > DP2 > DP3 > mDP4 > mDP5 > DP6
- DP1 > USB-C > DP3 > mDP4 > mDP5 > DP6
- DP1 > DP2 > VGA > mDP4 > mDP5 > DP6
- DP1> USB-C > VGA > mDP4 > mDP5 > DP6

Audio capability—Audio is supported on all DP ports except DP3.

Fixed issue

- FIWIOT-461—Computrace files that were in e-support image are removed in build 10.03.06.10.18.00.
- **WS-2482**—Apacer Solid-State Drives registry files are updated to resolve the blue screen error or BSOD in build 10.03.06.03.19.00.

Known issues

Table 10. Known issues

| Issue number | Description | Workaround |
|--------------|--|---------------|
| WC-684 | Citrix Receiver opens in the minimized mode in the Wyse Easy Setup shell. | No workaround |
| WC-652 | After performing HotPlug function on the DP1 port, display does not identify the first monitor when two monitors are connected. | No workaround |
| WC-633 | The window title for both About Dell Wyse Easy Setup Shell and About Dell Wyse Easy Setup Admin is displayed as About Dell Wyse Easy Setup. | No workaround |
| WC-630 | RDP connection window launched without enabling Full Screen option cannot be maximized. | No workaround |

Table 10. Known issues

| Issue number | Description | Workaround | |
|--------------|---|---|--|
| WC-603 | When you add or set the newly created user account in auto logon, the This user does not exist error message is displayed. | Logging into the account manually once will allow for subsequent logins to auto-login until the device is rebooted. | |
| WC-594 | Shrinkable OS volume alert window is displayed when you run the ConfigMgr Sysprep in the SCCM configuration. | If the volume shrinks, there is no impact to the device or the experience. | |
| WC-751 | Low memory issue observed when you play 4K videos using a local browser on multiple displays. | No workaround | |
| BITS368006 | Intel virtual monitor option is displayed in Display Settings when the Intel display port —DP1, DP2, or DP3 is hot plugged to AMD display port mDP4, mDP5, or DP6. | he Intel display port not plugged to AMD | |
| WC-590 | Speed and Duplex option is not displayed in the Ethernet Status properties. | No workaround | |
| WS-2252 | On Wyse 5070 thin client with 4 GB RAM, Unified Write Filter(UWF) cache size is updated to 2048 MB after upgrading the service image build. | To reset the cache size, do the following: 1. Log in as an administrator. 2. Disable the write filter. 3. Go to Systray and double-click the UWF icon. The UWF panel is displayed. | |
| | | Go to UWF Cache settings and click Default. The cache size is reset to 1024 MB. | |
| | | The cache size is reset to 1024 MID. | |

Supported peripherals

Table 11. Supported peripherals

| Audio | Dell Pro Stereo Headset - Skype for Business - UC350 | |
|--------|---|--|
| | Professional Sound Bar - Skype for Business - AE515 | |
| | Dell USB Sound Bar - AC511 | |
| | Jabra Pro 935 MS Wireless headset (Mono) - Office Centric | |
| Cables | DP to HDMI adapter | |
| | DP to VGA adapter | |
| | USB - C to DP adapter | |
| | USB - C to HDMI adapter | |
| | USB-C to VGA adapter | |
| | USB to Serial adapter - Trendnet | |
| | USB to Serial adapter - Cables-2-Go | |

Table 11. Supported peripherals

| Input devices | Dell USB Wired Keyboard - KB216 | | |
|---------------|---|--|--|
| | Dell USB Wired Optical Mouse - MS116 | | |
| | Dell USB Wired Keyboard with Smart Card reader - KB813 | | |
| | Dell Wireless Keyboard and Mouse - KM636 | | |
| | Dell USB Wired Laser mouse – Naruto | | |
| | Japanese Keyboard – KB216 | | |
| Monitors | Dell 24 Monitor - E2417H | | |
| | Dell 23 Monitor- E2318H | | |
| | Dell 22 Monitor - E2218HN | | |
| | Dell 20 Monitor - E2016H | | |
| | Dell 19 Monitor - E1916H | | |
| | Dell 24 Monitor - P2418HT (touch) | | |
| | Dell 24 Monitor - P2417H | | |
| | Dell 23 Monitor - P2317H | | |
| | Dell 22 Monitor - P2217H | | |
| | Dell 22 Monitor - P2217 | | |
| | Dell 20 Monitor - P2016 | | |
| | Dell 24 Monitor - U2415 | | |
| | Dell 43 Monitor - P4317Q | | |
| | Dell 24 Monitor - MR2416 | | |
| | Dell 24 Monitor - P2415Q 4K2K (UHD) monitor | | |
| | Dell UltraSharp 34 Monitor - P3418HW | | |
| | Dell UltraSharp 27 Monitor - U2518D | | |
| | Dell UltraSharp 27 Monitor - U2718Q (4K) | | |
| Networking | Add On 1000 Base-T SFP transceiver (RJ-45) - 310-7225-AO | | |
| | Allied Telesis 1 Gbps SFP transceiver - fiber connector - AT-SPSX-90 | | |
| | Allied Telesis 100 Mbps SFP fiber transceiver AT-SPFX/2-90 | | |
| | Allied Telesis 10/100/1000 RJ-45 SFP transceiver - copper (NOT TAA) - AT-SPTX | | |
| | Dell Finisar 1 GB SFP - FTLF8519P3BNL | | |
| | Dell Finisar 100 Mbps SFP - FTLF1217P2BTL-FC | | |

Used and free space details

Table 12. Used and free space details

| Platform | Flash size | Used space <drive c=""></drive> | Free space |
|--------------------------------|------------|---------------------------------|------------|
| Wyse 5070 thin client | 32 GB | 15.1 GB | 13.3 GB |
| Wyse 5070 extended thin client | 64 GB | 15.2 GB | 43 GB |

Operating system components

Table 13. Driver details

| Driver details | Version details for build 10.03.06.10.18.00 | Version details for build number 10.03.06.03.19.00 |
|----------------------|--|--|
| BIOS version | 1.1.3 | 1.1.4 |
| Display Adapter | AMD Radeon Graphics—23.20.768.0 | AMD Radeon Graphics—23.20.768.0 |
| | Intel UHD Graphics—23.20.16.4933 | Intel UHD Graphics—23.20.16.4933 |
| Ethernet Adapter | Realtek PCIe GBE Family Controller —10.21.811.2017 | Realtek PCIe GBE Family Controller—10.3.815.2018 |
| Audio | Intel Display Audio—10.24.0.3Realtek Audio—6.0.1.8378 | Intel Display Audio—10.24.0.3Realtek Audio10.0.149393.0 |
| Wireless Adapter | Intel® Wireless AC 9560—20.30.4.1 | Intel® Wireless AC 9560—20.30.4.1 |
| Bluetooth | Intel® Wireless Bluetooth®— 20.50.1.2 | Intel® Wireless Bluetooth®—20.50.1.2 |
| USB xHCl driver | AMD USB 3.0 eXtensible Host Controller 1.0 (Microsoft)— 10.0.14393.1794 | Intel® USB 3.0 extensible Host Controller 1.0 (Microsoft) —10.0.14393.1794 |
| Wyse RAM Disk driver | 5.0.2183.5 | 5.0.2183.5 |
| | By default, RAM disk size is 512 MB for thin clients with 8 GB RAM. | By default, RAM disk size is 512 MB for thin clients with 8 GB RAM. |
| Flash.sys | 1.0.7.11 | 1.0.7.11 |
| Dell Command Monitor | 9.3.1.320 | 9.3.1.320 |
| CAD-MAP-VDI | 1.0.0.1 | 1.0.0.1 |

Table 14. Common application, features, and files (continued)

| Application/features/ files | Version details for build 10.03.06.10.18.00 | Version details for build number 10.03.06.03.19.00 | |
|--------------------------------------|--|---|--|
| RDC | 10.0.14393—RDP 10.2 is supported | 10.0.14393—RDP 10.2 is supported | |
| Citrix Receiver—Standard | 14.11.0.17061 | 14.11.0.17061 | |
| | Citrix Online Plugin 14.11.0.17061 | Citrix Online Plugin 14.11.0.17061 | |
| Citrix HDX Real Time Media Engine | 2.4.0.1233 | 2.4.0.1233 | |
| VMware Horizon Client | 4.8.0.1562—In Dell Thin Client Application and Programs and Features | 4.8.0.1562—In Dell Thin Client Application and Programs and Features 4.8.0—In VMware Horizon Client | |

Table 14. Common application, features, and files (continued)

| Application/features/ files | Version details for build 10.03.06.10.18.00 | Version details for build number 10.03.06.03.19.00 | |
|---|--|--|--|
| | 4.8.0—In VMware Horizon Client | | |
| Ericom PowerTerm 12.0 Interconnect for Thin Clients | | 12.0 | |
| SCCM 2016 client | 5.00.8412.1307 | 5.00.8412.1307 | |
| Windows Media Player | 12.0.14393 | 12.0.14393 | |
| Internet Explorer | 11.00.14393 | 11.00.14393 | |
| Tight VNC | 2.6.4.0 | 2.6.4.0 | |
| Ericom connect web connect | 7.5.1 | 7.5.1 | |
| .NET Framework | 4.6.2 | 4.6 | |
| Wyse Device Agent | 14.2.0.51 | 14.2.0.51 | |
| Wyse Easy Setup | NA | 1.0.1.3289 | |
| Quick Start | NA | 1.0 | |
| Bit locker with TPM Supported by default. (i) NOTE: TPM 2.0 firmware is supported as a factory configuration. | | Supported by default. (i) NOTE: TPM 2.0 firmware is supported as a factory configuration. | |
| Windows Multi touch | Supported | Supported | |
| Windows Defender with antivirus definition | 1.271.1182.0 | 1.271.1182.0 | |
| Microsoft Management Console | Management Console 3.0 Version 1607—OS Build 14393.1884 | Management Console 3.0 Version 1607—OS Build 14393.1884 | |
| Microsoft Silverlight | 5.1.50907.0 | 5.1.50907.0 | |
| Background Intelligent Transfer Service (BITS) | Supported | Supported | |
| MSXML | Supported | Supported | |
| XML Paper Specification (XPS) | Supported | Supported | |
| Network Access Protection | Not Supported | Not Supported | |
| Credential Roaming | Supported | Supported | |
| WPA2 | Supported | Supported | |
| CredSSP | Supported | Supported | |

Table 14. Common application, features, and files

| Application/features/ files | | Version details for build 10.03.06.10.18.00 | Version details for build number 10.03.06.03.19.00 |
|--|-------------------------------|--|---|
| Dell Wyse Wallpaper on All Users | | Supported | Supported |
| DirectX | | 12 | 12 |
| DellThinClientAppli cation.exe—NewClient Application | | 10.0.0.15 | 10.0.0.21 |
| Unified Write Filter manager -Uwfmgr.exe—File Version | | 10.0.14393.1770 | 10.0.14393.2312 |
| UWF system tray UI - UWFTray.exe | | 1.0.4.6 | 1.0.4.12 |
| UWF Service - UWFSvc.exe | | 1.0.4.6 | 1.0.4.12 |
| Disk_Size.exe | | 3.0.0.5 | 3.0.0.5 |
| DeleteFreeSpace.exe | | 1.2.1.0 | 1.2.1.0 |
| Custom Sysprep support in scripts | | Supported | Supported |
| Windows Time Service | | Supported | Supported |
| FI Core changes | | Scripts changes are part of the build. | Scripts changes are part of the build. |
| CAD MAP Application DWKbFilter.sys DWKbFilterMon.exe DWKbFilterWatchdog. exe | | 2.3.0.1 2.2.0.4 2.2.0.4 | 2.3.0.1 2.2.0.4 2.2.0.4 |
| Microsoft Lync Vdi 2013 | | 15.0.4420.1017 | 15.0.4420.1017 |
| ALM.exe | Application Launch Manager | NA | In Control Panel > Programs and Features |
| | Application Launch Manager | NA | In Dell Thin Client Application > Client Information > Installed Products |
| | Application Launch Manager | NA | In C:\Program Files\ALM |
| XDCM.e xe | xData CleanUp Manager | NA | In Control Panel > Programs and Features |
| | xData CleanUp Manager | NA | In Dell Thin Client Application > Client Information > Installed Products |
| | XDataCleanupM anager | NA | In C:\Program Files\xDCM |

QFEs

The following QFEs are added as part of this release:

- KB4048953—build number 10.03.06.10.18.00
- KB4132216—build number 10.03.06.10.18.00
- KB4338832—build number 10.03.06.10.18.00
- KB4345418—build number 10.03.06.10.18.00
- KB4132216—build number 10.03.06.03.19.00
- KB4462930—build number 10.03.06.03.19.00
- KB4462917——build number 10.03.06.03.19.00

For more information, see support.microsoft.com.

© 2018 - 2019 Dell Inc. or its subsidiaries. All rights reserved. Dell, EMC, and other trademarks are trademarks of Dell Inc. or its subsidiaries. Other trademarks may be trademarks of their respective owners.