




EN FEATURES:


- Compact, considerate and retractable design ensures it can clamp various circuit boards of different thickness and variant length.
- 360° Adjustable Holder. The clammer can be adjusted freely (360°) according to the PC Board's position and the user's requirement.
- Light weight, easy to carry, this Clamping kit is convenient to carry with, and can be widely used in many areas like schools, labs, working shop, factories etc.
- Retractable shelf and knob to hold various sizes of PC Boards.

ASSEMBLY INSTRUCTIONS:

1. Unscrew the 4 screws of the shorter steel pipes
2. Put the longer steel pipe above the shorter pipes ("+" shape), and fix them with the screws properly.

HOW TO USE:

- Adjust the knob on the bottom side to get the target length of your PCB, then fix the knobs.
- Put your circuit board into a proper clamping mouth.
- Adjust the knob on the top side to get your target angle, then fix the knobs.
- Ready to solder and work on your circuit board easily.



IT CARATTERISTICHE:


- Compatto dal design retrattile, assicura il bloccaggio di varie schede di circuiti stampati di diversi spessori e lunghezze.
- Supporto Regolabile a 360°. Il morsetto può essere regolato liberamente (360°) in base alla posizione della scheda di circuiti e delle necessità dell'utente.
- Leggero, facile da trasportare, questo kit è ampiamente utilizzabile in molti settori di attività come scuole, laboratori, officine, fabbriche etc.
- Mensola e manopola sono retraibili per poter supportare varie misure di schede di circuiti stampati.

ISTRUZIONI DI MONTAGGIO:

1. Svitare le 4 viti inserite nelle barre di acciaio più corte.
2. Posizionare le barre più lunghe sopra le più corte, in maniera perpendicolare, in modo da creare una forma a croce e fissarle con le viti.

MODO D'USO:

- Regolare la manopola nella parte inferiore per ottenere la larghezza adatta per la scheda di circuiti stampati, poi serrare le manopole.
- Inserire la scheda in un morsetto.
- Regolare la manopola nella parte superiore per ottenere l'angolo desiderato, poi serrare le manopole.
- Tutto è pronto per poter saldare e lavorare facilmente sui circuiti stampati.



1. Circuit board (not included) / Scheda circuiti (non inclusa)
2. Clamp teeth / Morsetto
3. Angle adjust Knob / Manopola per regolare l'angolazione
4. Length adjust Knob / Manopola per regolare la lunghezza