

Windows 10 IoT Enterprise LTSC 2021

Release Notes



Notes, cautions, and warnings

 **NOTE:** A NOTE indicates important information that helps you make better use of your product.

 **CAUTION:** A CAUTION indicates either potential damage to hardware or loss of data and tells you how to avoid the problem.

 **WARNING:** A WARNING indicates a potential for property damage, personal injury, or death.

Contents

Chapter 1: Overview.....	6
Important Notes.....	6
Chapter 2: Version matrix	7
Chapter 3: Quarterly Release 2402.....	8
Release summary.....	8
Priority and recommendations.....	8
New and enhanced features.....	8
Compatibility.....	8
Build details	8
Test Environment.....	9
Dell value-added applications in Dell Application Store 24.02.0.5.....	9
Third-party applications.....	9
Fixed Issues.....	10
Chapter 4: Quarterly Release 2312.....	11
Release summary.....	11
New and enhanced features.....	11
Compatibility.....	12
Build details.....	12
Hardware Support information.....	13
Supported languages.....	14
Important notes.....	14
Test Environment.....	14
Used space and free space.....	15
QFEs list.....	15
Dell value-added applications in Dell Application Store 23.12.0.1	15
Operating System/Driver components.....	16
Fixed Issues.....	16
Known Issues.....	18
Peripherals ecosystem.....	18
Boot sequence.....	19
Chapter 5: Quarterly Release 2308.....	20
Release summary.....	20
New and enhanced features.....	20
Important notes.....	21
Post Installing Dell Application Store.....	21
Dell value-added applications in Dell Application Store.....	21
Driver components.....	21
Compatibility.....	21
Build details.....	21
Addendum.....	22

Chapter 6: Quarterly Release 2306.....	23
Release summary.....	23
New and enhanced features.....	23
Important notes.....	23
Post Installing Dell Application Store.....	23
Dell value-added applications in Dell Application Store.....	24
Driver components.....	24
Compatibility.....	24
Build details.....	24
Addendum.....	24
Chapter 7: Windows 10 IoT Enterprise LTSC 2021 10.05.XX.08.23.00.....	26
Release summary.....	26
New and enhanced features.....	26
Important notes.....	26
UWF Servicing Mode and Task Scheduler Information.....	26
Post Installing Dell Application Store.....	27
QFEs list.....	27
Dell value-added applications in Dell Application Store.....	27
Addendum.....	27
Dell value-added applications/Driver components.....	28
Test Environment.....	29
Compatibility.....	29
Build details.....	29
Chapter 8: Windows 10 IoT Enterprise LTSC 2021 10.05.XX.10.22.00.....	31
Release summary.....	31
New and enhanced features.....	31
Important notes.....	32
UWF Servicing Mode and Task Scheduler Information.....	32
Post Installing Dell Application Store.....	32
Dell Application Store- Citrix installation pre-requisite.....	32
QFEs list.....	32
Third-party and Dell value-added applications in Dell Application Store.....	33
Dell value-added applications/ Driver components.....	33
Test Environment.....	34
Compatibility.....	35
Build details.....	35
Chapter 9: Windows 10 IoT Enterprise LTSC 2021 10.05.XX.07.22.00	36
Release summary.....	36
New and enhanced features.....	36
Important notes.....	37
Citrix Desktop Viewer.....	37
Post Installing Dell Application Store.....	37
Task scheduler information to support Windows Defender Auto Updates	37
Dell Application Store- Citrix installation pre-requisite.....	37
QFEs list.....	37

Third-party & Dell value-added applications in Dell Application Store.....	38
Dell value-added applications/ Driver components.....	38
Test Environment.....	39
Compatibility.....	39
Build details.....	39
Chapter 10: Windows 10 IoT Enterprise LTSC 2021 10.05.XX.06.23.00	41
Release summary.....	41
New and enhanced features.....	41
Compatibility.....	41
Build details.....	41
Third-party applications in Dell Application Store.....	42
Hardware support information.....	42
Supported languages.....	43
Important notes.....	43
Test Environment.....	43
Used space and free space.....	44
QFEs list.....	44
Operating system/ Driver components.....	45
Peripherals ecosystem.....	46
Boot sequence.....	47
Chapter 11: Resources and support.....	48
Chapter 12: Contacting Dell.....	49

Overview

This document is intended for IT administrators and/or end users of Dell thin clients running Windows 10 IoT Enterprise LTSC 2021 operating system.

The document provides details on the enhancements, fixed issues, and new features on Dell thin clients which are available as e-support images, Dell Application Store (DAS) and/or other third-party application packages.

 **NOTE:** To determine which operating system version you must select for your device, see [Version matrix](#).

Important Notes

- Windows 10 IoT Config UI Enabler Package and the Wyse Device Agent (included in the Dell Application Store) components are moved to the specific product pages. You will no longer be able to download the components from the Wyse Management Suite support page. Going forward, all updates and maintenance that is related to these components will be centralized on the device product support page. For example, you can download the components from the [Drivers & Downloads](#) page of OptiPlex 3000 Thin Client.
- Dell value-added applications are installed by default when the Dell Application Store is installed.
- The .iso format is supported and available for image deployment through Wyse Management Suite and Dell OS Recovery Imaging tool.
- You can download individual third-party applications as add-ons from the [Dell Support](#) page and Wyse Management Suite cloud repository.
- Dell Application Store is separated from the e-support image on the [Dell Support](#) page. You must download the latest Dell Application Store from [Dell Support](#) page to receive the new features and enhancements.
- You can manage the Unified Write Filter tray user interface using the Dell Application Control Center.
- To manage the Unified Write Filter, right-click the Dell Application Control Center and select **Run as administrator**.
- Internet connection is required to install Microsoft Edge WebView2 Runtime as a prerequisite for Citrix Workspace Application 23.11.1.140.

Version matrix

The following version matrix lists the devices that are supported in each release of Windows 10 IoT Enterprise LTSC 2021:

Table 1. Version matrix

Release version	Release date	Supported devices	Release Notes
Dell Application Store—24.02.0.5	March 2024	<ul style="list-style-type: none"> • OptiPlex 3000 Thin Client • OptiPlex All-In-One 7410 • Latitude 3440 • Latitude 5440 • OptiPlex Micro Plus 7010 	Quarterly Release 2402
<ul style="list-style-type: none"> • Dell Application Store—23.12.0.1 • E-support image—10.05.XX.12.23.00 	December 2023	<ul style="list-style-type: none"> • OptiPlex 3000 Thin Client • OptiPlex All-In-One 7410 • Latitude 3440 • Latitude 5440 • OptiPlex Micro Plus 7010 	Quarterly Release 2312
Dell Application Store—23.08.0.4	August 2023	<ul style="list-style-type: none"> • OptiPlex 3000 Thin Client • OptiPlex All-In-One 7410 • Latitude 3440 • Latitude 5440 • OptiPlex Micro Plus 7010 	Quaterly Release 2308
Dell Application Store—23.06.0.0	June 2023	OptiPlex 3000 Thin Client	Quarterly Release 2306
E-support image—10.05.XX.10.22.00	October 2022	OptiPlex 3000 Thin Client	Windows 10 IoT Enterprise LTSC 2021
E-support image—10.05.XX.07.22.00	July 2022	OptiPlex 3000 Thin Client	Windows 10 IoT Enterprise LTSC 2021
E-support image—10.05.XX.02.22.00	March 2022	OptiPlex 3000 Thin Client	Windows 10 IoT Enterprise LTSC 2021

Quarterly Release 2402

Release summary

This release document provides comprehensive details on the latest version of the Dell Application Store version 24.02.

This new release introduces several enhancements and fixes targeting image deployments from Wyse Management Suite, Wyse Easy Setup, Wyse Device Agent (WDA), Dell Application Control Center (DACC), and product security. Each of these improvements is discussed in detail in the subsequent sections, providing a clear overview of what is new and improved in this release.

Version

Dell Application Store—24.02.0.5

Third-party applications—See [Third-party applications](#)

Release date

March 2024

Priority and recommendations

Dell Technologies recommends that you apply this update during your next scheduled update cycle. This release contains fixed issues for Windows 10 IoT Enterprise LTSC 2021.

New and enhanced features

- The Wyse Device Agent lock screen is enhanced to support multimonitor setup during Wyse Management Suite policy or configuration deployment. This enhancement is added to disable the option to close the lock screen using the Windows hotkeys such as ALT+F4, during the deployment of device management updates.
- The latest third-party applications are updated and are available at <https://www.dell.com/support> and the Wyse Management Suite cloud repository. For information about the version details, see [Third-party applications](#).

Compatibility

Build details

Table 2. Build details of Dell Application Store 24.02.0.5

DAS installer version	Build number	Wyse Management Suite package	Build size
24.02.0.5	24.02.0.5	DellApplicationStore_24.02.0.5.exe	109,666,304 bytes

Test Environment

Table 3. Test Environment

Hardware Type	Model Name	CPU Name	Build Package Name	Product Version	RAM	SSD Size	BIOS Version
OptiPlex 3000 Thin Client	OptiPlex 3000 Thin Client	Pentium, Celeron	WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso	10.05.X X.12.23.00	8/16 GB	256 GB	1.14.0
OptiPlex All-In-One 7410	OptiPlex All-In-One 7410	Pentium, Celeron	WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso	10.05.X X.12.23.00	8/16/32 GB	256 GB	1.11.0
Latitude 3440	Latitude 3440	Intel i3, Intel i5	WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso	10.05.X X.12.23.00	8/16/32 GB	256 GB	1.10.1
Latitude 5440	Latitude 5440	Intel i3, Intel i5	WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso	10.05.X X.12.23.00	8/16/32 GB	256 GB	1.10.0
OptiPlex Micro Plus 7010	OptiPlex Micro Plus 7010	Intel i5	WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso	10.05.X X.12.23.00	8/16/32 GB	256 GB	1.10.0

Dell value-added applications in Dell Application Store 24.02.0.5

Table 4. Dell value-added applications

Application name	Version	Updates
Wyse Easy Setup	2.0.0.619	Updated to resolve issues. For more information, see Fixed issues .
Wyse Device Agent	14.6.10.8	
Dell Application Control Center (DACC)	1.1.0.37	Copyright update
Application Launch Manager (ALM)	1.1.0.13	Copyright update
xData CleanUp Manager (xDCM)	1.0.0.10	Copyright update
Dell Overlay Optimizer	1.0.1.4024	No change
Language Configuration Tool	1.0.0.10	No change

Third-party applications

The following is the list of third-party applications available as individual add-on packages:

Table 5. Third-party applications

Application name	Version	Silent installation parameters
VMware Horizon Client (2309)	8.11.1.41306	--silent
Citrix Workspace app (2311.1)	23.11.1.140	--silent
Amazon WorkSpaces	5.17.04420	--silent

Table 5. Third-party applications (continued)

Application name	Version	Silent installation parameters
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.3.0.58378	/qn
Cisco Webex App VDI Plugin (Bundled Webex Meetings VDI plugin)	43.12.0.28497	/qn
Zoom VDI Universal plugin	5.16.24500	/quiet /norestart

Fixed Issues

The following issues are fixed after you install Dell Application Store 24.02.0.5 on the device.

Table 6. Fixed Issues

S. No.	Issue Description/Summary	Solution/Workflow
1	Wyse Easy Setup permits the addition of any file type as a custom icon for configured applications which results in a disruption of Wyse Easy Setup functionality.	Reconfigure Wyse Easy Setup to allow only .jpg, .png, .bmp, and .jfif options as File Type for custom icons.
2	An error notification is displayed when each time a Device Query is initiated on devices that are managed by WinIoT 2.x policy in Wyse Management Suite.	Use Wyse Management Suite version 4.2 or later to configure or send the commands from Wyse Management Suite.
3	The volume setting for the Plantronics Black Wire headset microphone does not persist in the Wyse Easy Setup KIOSK shell.	Reconfigure the microphone settings with the latest Wyse Easy Setup.
4	The Wyse Management Suite server does not update the last login user information correctly for Windows 10 IoT Enterprise LTSC 2021 devices.	Use Wyse Management Suite version 4.3 or later to manage the Windows 10 IoT Enterprise LTSC 2021 devices.
5	The Wyse Device Agent reports MQTT failure events to the Wyse Management Suite Public Cloud server.	Use Wyse Management Suite version 4.2 or later in the cloud environment to manage the Windows 10 IoT Enterprise LTSC 2021 devices.
6	The WinIoT 2.x policy from Wyse Management Suite for power settings does not persist on Dell Latitude 3440 and Latitude 5440 devices after reboot.	Use Wyse Management Suite version 4.2 or later to apply the WinIoT 2.x policy.
7	When you initiate a Windows update with the Unified Write Filter enabled, the device starts to download the updates and fill up the write filter and trigger a reboot loop.	No additional steps are required.
8	The incorrect product labels are updated in the Wyse Management Suite device information dashboard.	No additional steps are required.
9	Azure Virtual Desktop description and configuration title is updated to Azure Virtual Desktop (AVD) in Wyse Management Suite for a seamless search experience.	No additional steps are required.

Quarterly Release 2312

Release summary

This release note contains information about the Dell Application Store 23.12.0.1 and e-support images 10.05.XX.12.23.00 release for Windows 10 IoT Enterprise LTSC 2021 that runs on the OptiPlex 3000 Thin Client, OptiPlex All-In-One 7410, Latitude 3440, Latitude 5440, and OptiPlex Micro Plus 7010 platforms. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager for the updated [Dell value-added applications](#). The Windows 10 IoT Enterprise LTSC 2021 supports English and [other MUI languages](#).

Version

Dell Application Store - 23.12.0.1

E-support images - 10.05.XX.12.23.00

Release date

December 2023

New and enhanced features

- [Dell Application Store](#) 23.12.0.1 and e-support images 10.05.XX.12.23.00 include the latest Dell value-added applications addressing few issues and bugs. For more information, see [Fixed issues](#).
- Dell Technologies recommends that you apply this update during your next scheduled update cycle. This release contains fixed issues for Windows 10 IoT Enterprise LTSC 2021.
- E-support images are released to address the Intel Graphics Tray application error message that is displayed during every boot.

Table 7. E-support images 10.05.XX.12.23.00

Image Name	Supported platforms
WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso	OptiPlex 3000 Thin Client
WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso	OptiPlex All-in-One 7410
WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso	Latitude 3440
WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso	Latitude 5440
WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso	OptiPlex Micro Plus 7010

- It includes Wyse Device Agent version 14.6.10.5 to support Azure Blob Storage with Autoscaling. For more information about the support for Azure Blob Storage with autoscaling, see Dell Wyse Management Suite 4.x release notes at [Dell Support](#). Wyse Device Agent enables endpoints to adapt to the downloading way of Azure Blob. Azure Blob Storage with Autoscaling is supported from Wyse Management Suite version 4.2 and later versions.
- E-support image 10.05.XX.12.23.00 is updated to include the latest security intelligence updates for Microsoft Defender Antivirus and other Microsoft anti-malware updates. For more information, see [QFEs list](#).
- Support for updated `ConfigUISupport.exe` v1.0.0.8 which is a WinIoT Config UI enabler package to support migration to WinIoT 2.x policy after Dell Application Store 23.12.0.1 is installed and latest e-support image 10.05.XX.12.23.00 deployment.
 - If the system is already supporting and migrated to WinIoT 2.x policy, you must not deploy the `ConfigUISupport.exe` v1.0.0.8 again.

- If the system is re-imaged with the platform's latest e-support image 10.05.XX.12.23.00, installed with the latest Dell Application Store 23.12.0.1 and then you plan to migrate to support WinIoT 2.x policy, then use the ConfigUISupport.exe v1.0.0.8 for migrating the client to support WinIoT 2.x policy.
- (i) NOTE:** Wyse Device Agent version 14.6.9.26 and later versions are required to support Wyse Management Suite silent installation for Third party add-on and Dell Application Store 23.12.0.1.
- (i) NOTE:** Dell value-added applications are installed by default when the Dell Application Store 23.12.0.1 is installed.
- (i) NOTE:** Support of ISO format on Imaging support from Wyse Management Suite and [Dell OS Recovery Imaging Tool](#) for Imaging operations.
- (i) NOTE:** You can download individual third party applications as add-on from the [Dell Support](#) page.
- (i) NOTE:** Dell Application Store 23.12.0.1 is separated from the e-support image 10.05.XX.12.23.00 on the Dell Support page. You must download the latest Dell Application Store 23.12.0.1 from [Dell Support](#) page to get the above enhancements.
- (i) NOTE:** The Unified Write Filter tray user interface is managed by the Dell Application Control Center.
- (i) NOTE:** Right-click and run as administrator when you start Dell Application Control Center to continue managing Unified Write Filter.

Compatibility

Build details

Dell Application Store 23.12.0.1 runs on the following operating systems:

Table 8. Supported operating systems and platforms

Supported operating systems	Platforms
Windows 10 IoT Enterprise LTSC 2021	OptiPlex 3000 Thin Client
	OptiPlex All-In-One 7410
	Latitude 3440
	Latitude 5440
	OptiPlex Micro Plus 7010

Table 9. Build details of Dell Application Store 23.12.0.1

DAS installer version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)
23.12.0.1	23.12.0.1	DellApplicationStore_23.12.0.1.exe	109,617,152 bytes

The following are the build details for e-support images 10.05.XX.12.23.00:

Table 10. General build details

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent Version
OptiPlex 3000 Thin Client	WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso	10.0	10.05.XX.12.23.00	English	4.3.0
OptiPlex All-In-One 7410	WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso	10.0	10.05.XX.12.23.00	English	4.3.0

Table 10. General build details (continued)

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent Version
Latitude 3440	WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso	10.0	10.05.XX.12.23.00	English	4.3.0
Latitude 5440	WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso	10.0	10.05.XX.12.23.00	English	4.3.0
OptiPlex Micro Plus 7010	WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso	10.0	10.05.XX.12.23.00	English	4.3.0

Table 11. Platform specific build details of Wyse Management Suite

Platform(s)	Version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	Localization	BIOS Details
OptiPlex 3000 Thin Client	10.0	10.05.XX.12.23.00	WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso	12,912,885,760 (WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso)	English	1.14.0
OptiPlex All-In-One 7410	10.0	10.05.XX.12.23.00	WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso	12,854,362,112 (WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso)	English	1.10.0
Latitude 3440	10.0	10.05.XX.12.23.00	WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso	12,858,032,128 (WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso)	English	1.9.1
Latitude 5440	10.0	10.05.XX.12.23.00	WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso	12,858,032,128 (WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso)	English	1.10.0
OptiPlex Micro Plus 7010	10.0	10.05.XX.12.23.00	WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso	12,456,951,808 (WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso)	English	1.10.0

 **NOTE:** BIOS is not part of this build. The above BIOS version is used during the build validation.

Hardware Support information

This section provides the hardware support information.

- OptiPlex 3000 Thin Client - 8/16 GB RAM, 256 GB SSD
- OptiPlex All-In-One 7410 - 8/16/32 GB RAM, 256 GB SSD
- Latitude 3440 Client - 8/16/32 GB RAM, 256 GB SSD
- Latitude 5440 Client - 8/16/32 GB RAM, 256 GB SSD
- OptiPlex Micro Plus 7010 - 8/16 GB RAM, 256 GB SSD

Table 12. Supported displays

Hardware	Operating System	Single Display (in built)	Dual Display
<ul style="list-style-type: none"> OptiPlex 3000 Thin Client OptiPlex All-in-One 7410 Latitude 3440 Latitude 5440 OptiPlex Micro Plus 7010 	Windows 10 IoT Enterprise LTSC 2021	Supported	Supported

Supported languages

- English (en-US)
- German (de-DE)
- French France (fr-FR)
- French Canada (fr-CA)
- Italian (it-IT)
- Spanish (es-ES)
- Japanese (ja-JP)
- Korean (ko-KR)
- Chinese Simplified (zh-CN)
- Chinese traditional (zh-TW)
- Brazilian Portuguese (pt-BR)
- Dutch Netherlands (nl-NL)
- Danish Denmark (da-DK)
- Finnish Finland (fi-FI)
- Norwegian Norway (nb-NO)
- Russian Russia (ru-RU)
- Swedish Sweden (sv-SE)

Important notes

Test Environment

Table 13. Test Environment

Hardware Type	Model Name	CPU Name	Build Package Name	Product Version	RAM	SSD Size	BIOS Version
OptiPlex 3000 Thin Client	OptiPlex 3000 Thin Client	Pentium, Celeron	WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso	10.05.XX.12.23.00	8/16 GB	256 GB	1.14.0
OptiPlex 7410 All-In-One Thin Client	OptiPlex 7410 All-In-One Thin Client	Pentium, Celeron	WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso	10.05.XX.12.23.00	8/16/32 GB	256 GB	1.10.0
Latitude 3440	Latitude 3440	Intel i3, Intel i5	WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso	10.05.XX.12.23.00	8/16/32 GB	256 GB	1.9.1
Latitude 5440	Latitude 5440	Intel i3, Intel i5	WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso	10.05.XX.12.23.00	8/16/32 GB	256 GB	1.10.0
OptiPlex Micro Plus 7010	OptiPlex Micro Plus 7010	Intel i5	WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso	10.05.XX.12.23.00	8/16/32 GB	256 GB	1.10.0

Used space and free space

Table 14. Used space and free space

Platform	SSD	Used space	Free space
OptiPlex 3000 Thin Client	256 GB SSD	15 GB	218 GB
OptiPlex 7410 All-In-One	256 GB SSD	15 GB	218 GB
Latitude 3440 Client	256 GB SSD	16 GB	217 GB
Latitude 5440 Client	256 GB SSD	16 GB	217 GB
OptiPlex Micro Plus 7010	256 GB SSD	14 GB	219 GB

QFEs list

Table 15. QFEs list for OptiPlex 3000 Thin Client, OptiPlex 7410 All- In-One, Latitude 3440, Latitude 5440

KB Number	Update Description
KB5003791	Update for Windows 10 IoT Enterprise LTSC 2021
KB5005699	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5031988	Update for Windows 10 IoT Enterprise LTSC 2021
KB5012170	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5032189	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5014032	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5032392	Update for Windows 10 IoT Enterprise LTSC 2021

Table 16. QFEs list for OptiPlex Micro Plus 7010

KB Number	Update Description
KB5003791	Update for Windows 10 IoT Enterprise LTSC 2021
KB5005699	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5029923	Update for Windows 10 IoT Enterprise LTSC 2021
KB5012170	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5030211	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5014032	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB50329709	Update for Windows 10 IoT Enterprise LTSC 2021

Dell value-added applications in Dell Application Store 23.12.0.1

Table 17. Dell value-added applications

Application name	Version
Wyse Easy Setup	2.0.0.567
Dell Application Control Center (DACC)	1.1.0.36
Application Launch Manager (ALM)	1.1.0.11
Dell Overlay Optimizer	1.0.1.4024
Language Configuration Tool	1.0.0.10

Table 17. Dell value-added applications (continued)

Application name	Version
xData CleanUp Manager (xDCM)	1.0.0.8
Wyse Device Agent	14.6.10.5

Operating System/Driver components

Table 18. Dell value-added applications driver details

Drivers/ Files	Version
CAD-MAP-VDI	3.0.6.0

Table 19. Common application, features, and files- part of e-support image 10.05.XX.12.23.00

Application	Version
Wyse Device Application (WDA)	14.6.10.5
PlatVsys	1.0.0.6
VMware Horizon Client (2212)	8.8.0.33776
Merlin	4.1.3
Wyse Easy Setup	2.0.0.567
Application Launch Manager (ALM)	1.1.0.11
xData CleanUpManager (xDCM)	1.0.0.8
Dell Command Monitor (DCM)	10.9.0.307
Citrix Workspace app 2303.1	23.3.0.55
Control Alt Del Map (CAD Map)	3.0.6.0
Build Content	1.0.0.8
Language Configuration Tool	1.0.0.10
Dell Application Control Center (DACC)	1.1.0.36
Azure Virtual Desktop	1.2.4763.0
Microsoft Edge Browser	119.0.2151.72
Microsoft Remote Desktop Connection	10.0.19041 (Protocol10.8 Supported)
TightVNC (Virtual NetworkComputing)	2.8.75.0

 **NOTE:** Factory image version number changes based on the production month and the year.

Fixed Issues

The following are the fixed issues:

Table 20. Fixed Issues

S. No.	Issue Description/Summary	Solution/Workflow
1	<ul style="list-style-type: none"> Wyse Easy Setup error message is displayed when Wyse Management Suite WinIoT policy is applied with Citrix Workspace application v2307. 	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.

Table 20. Fixed Issues (continued)

S. No.	Issue Description/Summary	Solution/Workflow
1	<ul style="list-style-type: none"> Wyse Easy Setup stops responding when an IT administrator uses a configuration with - or . in the hostname of the server URL and deploys a Win10 IoT 1.x policy. 	For the Citrix Workspace application error message, install the latest Citrix Workspace application version 2309 or later from Citrix website . i NOTE: To deploy the new Citrix Workspace application, see <i>Create and deploy standard application policy to thin clients</i> in the Wyse Management Suite admin guide.
2	Wyse Easy Setup stops responding when an IT administrator uses a configuration with - or . in the hostname or domain name of the server URL and deploys a Win10 IoT 2.x policy.	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.
3	You are unable to import an application file (.exe) with a name in Japanese characters in Wyse EasySetup.	Install the Dell Application Store 23.12.0.1 on the device.
4	WinIoT 2.x configuration from Wyse Management Suite 4.1 does not accept dots in Fully Qualified Domain Name (FQDN) for RD Gateway Server in Cloud Wyse Management Suite.	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.
5	When the WinIoT 2.x policy from Wyse Management Suite is applied for autologin settings, then your device enters into the reboot loop.	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.
6	WinIoT 2.x policy from Wyse Management Suite for power settings is failed to apply on Dell Latitude 3440 and 5440 devices.	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.
7	After you apply the WinIoT 2.x policy, then if you are ready to update your client, Update Now message is displayed after every restart.	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.
8	Windows hotkeys are enabled on the local Wyse EasySetup shell when the VMware Horizon session is locked and then you log out of the session, then you are not able to use p, x, l, and o characters to enter into the session again.	<ol style="list-style-type: none"> Install the Dell Application Store 23.12.0.1 on the device. Use Wyse Management Suite version 4.2 to apply the WinIoT 2.x policy.
9	The Intel Graphics Experience error message is displayed at every boot on devices which you have received as part of the shipments from Dell factory or after applying the e-support images which are posted on Dell Support page and are listed below. <ul style="list-style-type: none"> WinIoT_LTSC_2021_OptiPlex_3000_Aug2023.iso WinIoT_LTSC_2021_OptiPlex_7410_June2023.iso WinIoT_LTSC_2021_Latitude_3440_Sept2023.iso WinIoT_LTSC_2021_Latitude_5440_Aug2023.iso WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Aug2023.iso 	Deploy the latest e-support images 10.05.XX.12.23.00 for the respective platform that is listed below. <ul style="list-style-type: none"> WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso WinIoT_LTSC_2021_OptiPlex_AIO_7410_Dec2023.iso WinIoT_LTSC_2021_Latitude_3440_Dec2023.iso WinIoT_LTSC_2021_Latitude_5440_Dec2023.iso WinIoT_LTSC_2021_OptiPlex_MicroPlus_7010_Dec2023.iso
10	You are unable to pull an image using Wyse Management Suite from OptiPlex 3000 Thin Client.	Deploy the latest e-support image 10.05.XX.12.23.00 WinIoT_LTSC_2021_OptiPlex_3000_Dec2023.iso for the Dell OptiPlex 3000

Table 20. Fixed Issues (continued)

S. No.	Issue Description/Summary	Solution/Workflow
		<p>Thin Client which is on Dell Support page.</p> <p>(i) NOTE: To deploy the latest e-support image, use Dell OS Recovery Imaging Tool for Imaging operations.</p>

Known Issues

The following are the known issues:

Table 21. Known Issues

S. No.	Issue Description/Summary	Workaround if any
1	Wyse Device Agent (WDA) icon is observed for Citrix connection on the taskbar in Wyse Easy Setup KIOSK Shell.	Not Applicable
2	RDP icon is preserved on the Wyse Easy Setup Shell taskbar even after exiting the RDP session connection.	Not Applicable
3	The previous WinIoT 2.x policy configurations are removed after you restart device through Wyse Easy Setup KIOSK Shell.	You can log off and log in back to the device through Wyse Easy Setup KIOSK Shell.
4	Wyse Easy Setup KIOSK shell is not loaded after you run the Imaging process.	You can log off and log in back to the device through Windows Start Menu.
5	The device has Microsoft Edge as the default browser but when you deploy the latest e-support images 10.05.XX.12.23.00 or create a golden image by running Sysprep then the default browser application changes to the Internet Explorer in the Default apps settings.	<p>Do the following:</p> <ol style="list-style-type: none"> 1. Log in as an administrator. 2. Disable Unified Write Filter (UWF). 3. Go to Start Menu. 4. Click Settings > Default apps. 5. Select Microsoft Edge as the Web browser. 6. Click Apply. 7. Enable Unified Write Filter (UWF).

Peripherals ecosystem

Table 22. Peripherals ecosystem

Product Category (Module)	Product Description
Monitors	Dell 27 USB-C HUB Monitor
	Dell 22 Monitor
	Dell 24 Monitor
	Dell 24 USB-C Hub Monitor
	Dell UltraSharp 24 Monitor
Audio	Dell Pro Wireless Headset - Daybreak
	Dell Slim Conferencing Soundbar
	Dell Speakerphone
	Dell Stereo Headset

Table 22. Peripherals ecosystem (continued)

Product Category (Module)	Product Description
Input Devices	Dell Pro Wireless Keyboard and Mouse Dell Active Pen Dell Full-Size Wireless Mouse Dell Mobile Pro Wireless Mice Dell Multi-Device Wireless Keyboard Dell Multi-Device Wireless Keyboard and Mouse Combo Dell Multi-Device Wireless Mouse Dell Multimedia Keyboard Dell Optical Mouse Dell Palm Rest for KB216 and KM636 Dell Premier Multi-Device Wireless Keyboard and Mouse Dell Active Pen
Cables, Dongles, Adapters	Dell 7-in-1 USB-C Multiport Adapter 100W Adapter Type-C AC adapter
Webcam	Dell Pro Webcam
Docks & Port Replicators	Dell USB-C Dock

Boot sequence

- The first boot is Windows Boot Manager.
- The second boot is Merlin Non-Pxe.
- The third boot is UEFI HTTPS Boot.
- The fourth boot is UEFI CL1-3D256-Q11 NVMe SSTC 256 GB TWOTN2CC9DH000BB09161.
- The fifth boot is ONBOARD NIC (IPV4).
- The sixth boot is ONBOARD NIC (IPV6).

Quarterly Release 2308

Release summary

This release note contains information about the Dell Application Store 2308 for Windows 10 IoT Enterprise LTSC 2021. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager for the updated [Dell value-added applications](#). The Windows 10 IoT Enterprise LTSC 2021 supports English and [other MUI languages](#).

Version

23.08.0.4

Release date

September 2023

New and enhanced features

- Adherence to SDL 7.0 process controls.
 - [Dell value-added applications](#) are adhered to SDL 7.0 technical controls.
 - [Dell Application Store](#) supports silent installation (No installation parameter is required) from Wyse Management Suite.
 - [ConfigUISupport.exe](#) supports silent installation (No installation parameter is required) from Wyse Management Suite.
 - [Third party applications](#) support silent installation (No installation parameter is required) from Wyse Management Suite.
- i | NOTE:** Wyse Device Agent with version 14.6.9.22 or later is required to support WMS silent installation for Third party add-on and Dell Application Store.
- Third party applications and Dell Application Store package availability in Wyse Management Suite Cloud Repository.
 - The latest e-support image in ISO format for the OptiPlex 3000 Thin Client is available for download in the [Dell Support](#) page. This is to align with the annual e-support image release. [Click here](#) for release information about e-support image for OptiPlex 3000 Thin Client.
 - *Windows 10 IoT Enterprise LTSC 2021 Operating System Recovery Guide* is posted in the [Dell Support](#) under the documentation section of the OptiPlex 3000 Thin Client platform page. The image pull process is updated.
 - *Transition from the WinIoT-WES policy to WinIoT 2.x* whitepaper is posted in the [Dell Support](#) page. The document provides step-by-step instructions and FAQs on transitioning from the legacy WinIoT (WES) policy to the new WinIoT 2.x policy in WMS. For more information, go to the documentation section of the respective platform page.
- i | NOTE:** The new and upcoming features in WMS are available through WinIoT 2.x policy only. WinIoT 2.x policy is applicable only on Windows 10 IoT Enterprise LTSC 2021.
- i | NOTE:** Minimum version 14.6.9.22 is required to support WMS silent installation for Third party add-on and Dell application Store application.
- i | NOTE:** Dell value-added applications are installed by default when the Dell Application Store is installed.
- i | NOTE:** You can download individual third party applications as add-on from the [Dell Support](#) page.
- i | NOTE:** Dell Application Store is separate from the e-support image on the Dell Support page. You must download the latest Dell Application Store from [Dell Support](#) page to get the above enhancements.
- i | NOTE:** When Dell Application Store v23.06.0.2 is installed, it removes the RAMDisk drive (Z:\).

Important notes

Post Installing Dell Application Store

- After you run the Dell Application Store, the Unified Write Filter tray user interface is managed by the Dell Application Control Center.
- Right click and run as administrator when you start Dell Application Control Center to continue to manage Unified Write Filter.

Dell value-added applications in Dell Application Store

Table 23. Dell value-added applications

Application name	Version
Wyse Easy Setup	2.0.0.515
Dell Application Control Center (DACC)	1.1.0.35
Application Launch Manager (ALM)	1.1.0.11
Dell Overlay Optimizer	1.0.1.4023
Language Configuration Tool	1.0.0.10
xData CleanUp Manager (xDCM)	1.0.0.8
Wyse Device Agent	14.6.9.23

Driver components

Table 24. Dell value-added applications driver details

Drivers/ Files	Version
CAD-MAP-VDI	3.0.6.0

Compatibility

Build details

Dell Application Store runs on the following operating systems:

Table 25. Supported operating systems and platforms

Supported operating systems	Platforms
Windows 10 IoT Enterprise LTSC 2021	OptiPlex 3000 Thin Client
	OptiPlex 7410 AIO
	Latitude 3440
	Latitude 5440
	OptiPlex Micro Plus 7010

Table 26. Build details of Dell Application Store

DAS installer version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)
23.08.0.4	23.08.0.4	DellApplicationStore_23.08.0.4.exe	10,94,24,056 bytes

Addendum

List of Third-Party Applications available as individual Add-on packages

Table 27. Addendum

Application name	Version
VMware Horizon Client (2306)	8.10.0.37268
Citrix Workspace App (2307.1)	23.7.1.18
Amazon Workspaces	5.12.0.4246
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.1.4.57909
Cisco Webex VDI (Virtual Desktop Infrastructure) Meetings Plugin	42.2.6.11
Cisco Webex VDI (Virtual Desktop Infrastructure) Plugin	43.4.0.25959
Zoom VDI (Virtual Desktop Infrastructure) Plugin	5.15.4

Quarterly Release 2306

Release summary

This release note contains information about the Dell Application Store 2306 for Windows 10 IoT Enterprise LTSC 2021. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager for the updated [Dell value-added applications](#). The Windows 10 IoT Enterprise LTSC 2021 supports English and [other MUI languages](#).

Version

23.06.0.0

Release date

June 2023

New and enhanced features

- Third-party application has been separated from Dell Application Store, and as a consequence, Dell Application Store now only contains Dell value-added applications.
- The Dell Application Store package size is reduced from 1.4GB to around 104 MB. With a smaller footprint of Dell application store, it is also easier and faster to deploy Dell value-added applications.
- Third Party Applications are available as individual Add-on packages and as applications downloadable from [Dell Support](#) page.
- Adherence to SDL 7.0 process controls.
 - IT admins must provide admin or user account and passwords during custom image creation in the Dell Application Control Center.

(i) | NOTE: Dell value-added Applications are installed by default when the Dell Application Store is installed.

(i) | NOTE: Users can download individual third party applications as Add-on from [Dell Support](#) page.

(i) | NOTE: Dell Application Store is separate from the e-support image on Dell Support page. Customers need to download the latest Dell Application Store from [Dell Support](#) page to get the above enhancements.

(i) | NOTE: When Dell Application Store v23.06.0.2 is installed, it will remove the RAMDisk drive (Z:\\").

Important notes

Post Installing Dell Application Store

- After running the Dell Application Store, the Unified Write Filter tray user interface will be managed by Dell Application Control Center.
- Right click and run as administrator when starting Dell Application Control Center to continue to manage Unified Write Filter.

Dell value-added applications in Dell Application Store

Table 28. Dell value-added applications

Application name	Version
Wyse Easy Setup	2.0.0.471
Dell Application Control Center (DACC)	1.1.0.33
Application Launch Manager (ALM)	1.1.0.10
Dell Overlay Optimizer	1.0.1.4023
Language Configuration Tool	1.0.0.10
xData CleanUp Manager (xDCM)	1.0.0.8
Wyse Device Agent	14.6.9.21

Driver components

Table 29. Dell value-added applications driver details

Drivers/ Files	Version
CAD-MAP-VDI	3.0.6.0

Compatibility

Build details

Dell Application Store runs on the following operating systems:

Table 30. Supported operating systems and platforms

Supported operating systems	Platforms
Windows 10 IoT Enterprise LTSC 2021	OptiPlex 3000 Thin Client

Table 31. Build details of Dell Application Store

DAS installer version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	MD5 File Checksum
23.06.0.2	23.06.0.2	DellApplicationStore_23.06.0.2.exe	10,93,12,352 bytes	698C52E995A0C1091C26260737DA50A1

Addendum

List of Third-Party Applications available as individual Add-on packages

Table 32. Addendum

Application name	Version
VMWare Horizon Client (2303)	8.9.0.35399
Citrix Workspace App (2303)	23.3.0.55
Amazon Workspaces	5.9.0

List of Third-Party Applications available as individual applications

Table 33. Addendum

Application name	Version
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.1
Cisco WebEx VDI ((Virtual Desktop Infrastructure) Meetings Plugin	42.2.6.11
Cisco WebEx VDI (Virtual Desktop Infrastructure) Plugin	43.4.0.25959
Zoom VDI (Virtual Desktop Infrastructure) Plugin	5.14.10.23670

Windows 10 IoT Enterprise LTSC 2021

10.05.XX.08.23.00

Release summary

This release note contains information about the Windows 10 IoT Enterprise LTSC 2021 that runs on the OptiPlex 3000 Thin Client. Windows 10 IoT Enterprise LTSC 2021 is factory installed on the OptiPlex 3000 Thin Client. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager. The Windows 10 IoT Enterprise LTSC 2021 supports English and MUI languages.

Version

10.05.XX.08.23.00

Release date

September 2023

New and enhanced features

This release consists of two parts: the Dell Application Store and the E-support .iso image.

- Dell Application Store
 - Dell Application Store is separate from the e-support image on [Dell Support](#) page. You must download the latest Dell Application Store from [Dell Support](#) page to get the [New Features and Enhancements](#).
- E-support image
 - The e-support image is updated to include the latest security intelligence updates for Microsoft Defender Antivirus and other Microsoft anti-malware updates. See [QFEs list](#) for more information.
 - Secure Unique Password update for Windows 10 IoT Enterprise LTSC 2021.
 - **i | NOTE:** The default password for the Admin account is Admin#SerialNumber of the device. The default password for the User account is User#Serialnumber of the device.
 - Adherence to SDL 7.0 process controls.
 - [Dell value-added applications](#) are adhered to SDL 7.0 technical controls.
 - Supports [Dell OS Recovery Imaging Tool](#) for Imaging operations.
 - Dell Thin Client Application, RAMDisk, Dell Secure Client, and Quick Start applications are removed.

i | NOTE: If IT administrators do not plan to reload the e-support image, they can also download the security patches from [Microsoft Update Catalog](#) and follow the [Deployment Guide](#) for deployment. It can save time in deployment, image customization, and network traffic.

Important notes

UWF Servicing Mode and Task Scheduler Information

- Install the July 12 update, [2022-KB5015807](#) as a pre-requisite QFE to function UWF Servicing mode.

- 'WindowsUWServicing' is the scheduled task which is added and disabled by default to run at 3:00 AM every Sunday every 4 weeks for automatic windows updates.
- IT administrators can enable and update the scheduled timings as per their convenience.
- For UWServicing Mode, the device must be able to connect the Windows Updates servers.

Post Installing Dell Application Store

- After you run the Dell Application Store, the Unified Write Filter tray user interface is managed by Dell Application Control Center.
 - Right click and run as admin when starting Dell Application Control Center to continue to manage Unified Write Filter.
- i** **NOTE:** If you are using the latest 10.05.XX.08.23.00 e-support image, then Dell Thin Client Application is removed. Instead, Dell Application Control Center is added as part of the e-support image for device configuration and management.

QFEs list

Table 34. QFEs list

KB Number	Update Description
KB5003791	Update for Windows 10 IoT Enterprise LTSC 2021
KB5005699	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5027122	Update for Windows 10 IoT Enterprise LTSC 2021
KB5012170	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5028166	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5014032	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5028318	Update for Windows 10 IoT Enterprise LTSC 2021

Dell value-added applications in Dell Application Store

Table 35. Dell value-added applications

Application name	Version
Wyse Easy Setup	2.0.0.515
Dell Application Control Center (DACC)	1.1.0.35
Application Launch Manager (ALM)	1.1.0.11
Dell Overlay Optimizer	1.0.1.4023
Language Configuration Tool	1.0.0.10
xData CleanUp Manager (xDCM)	1.0.0.8
Wyse Device Agent	14.6.9.23

Addendum

List of Third-Party Applications available as individual Add-on packages

Table 36. Addendum

Application name	Version
VMware Horizon Client (2306)	8.10.37268
Citrix Workspace App (2307.1)	23.7.1.18

Table 36. Addendum (continued)

Application name	Version
Amazon Workspaces	5.12.0.4246
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.1.4.57909
Cisco Webex VDI (Virtual Desktop Infrastructure) Meetings Plugin	42.2.6.11
Cisco Webex VDI (Virtual Desktop Infrastructure) Plugin	43.4.25959
Zoom VDI (Virtual Desktop Infrastructure) Plugin	5.15.4

Dell value-added applications/Driver components

Table 37. Dell value-added applications driver details

Drivers/ Files	OptiPlex 3000 Thin Client
CAD-MAP-VDI	3.0.6.0

Table 38. Common application, features, and files-part of e-support image build 10.05.XX.08.23.00

Application	Version
Wyse Device Application (WDA)	14.6.9.23
PlatVsys	1.0.0.6
Citrix Workspace App (2307.1)	8.10.37268
Merlin	4.1.3
Wyse Easy Setup	2.0.0.515
Application Launch Manager (ALM)	1.1.0.11
xData CleanUp Manager (xDCM)	1.0.0.8
Dell Command Monitor (DCM)	10.9.0.307
Citrix Workspace 2307.1	23.7.1.18
Control Alt Del Map (CAD Map)	3.0.6.0
Build Content	1.0.0.8
Language Configuration Tool	1.0.0.10
Dell Application Control Center	1.1.0.35
Azure Virtual Desktop	1.2.4419.0
Microsoft Edge Browser	114.0.1823.79
Microsoft Remote Desktop Connection	10.0.19041 (Protocol 10.8 Supported)
TightVNC (Virtual Network Computing)	2.8.75

 **NOTE:** Factory image version number changes based on the production month and the year.

Test Environment

Table 39. Test Environment

Hardware Type	Hardware Rev	Model Name	CPU Name	Build Package Name	Product Version	RAM	SSD Size	BIOS Version
OptiPlex 3000 Thin Client	0502	OptiPlex 3000 Thin Client	Pentium	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_Oct2022.exe	10.05.09.10.22.00	8/16 GB	256 GB	1.5.0
OptiPlex 3000 Thin Client	0503	OptiPlex 3000 Thin Client	Celeron	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_Oct2022.exe	10.05.10.10.22.00	8/16 GB	256 GB	1.5.0
OptiPlex 3000 Thin Client	0502	OptiPlex 3000 Thin Client	Pentium	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_July2022.exe	10.05.09.07.22.00	8/16 GB	256 GB	1.5.0
OptiPlex 3000 Thin Client	0503	OptiPlex 3000 Thin Client	Celeron	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_July2022.exe	10.05.10.07.22.00	8/16 GB	256 GB	1.5.0

Compatibility

Build details

Table 40. General build details

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent version	Merlin USB Imaging Tool	Dell OS Recovery Tool
OptiPlex 3000 Thin Client	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_Aug2023.iso	10.0	10.05.XX.08.23.00	English	4.1.3	3.5.0.210	2.3.7515

Table 41. Platform specific build details of Wyse Management Suite

Platform(s)	Version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	Localization	BIOS Details	Platform	BIOS Version
OptiPlex 3000 Thin Client	10.0	10.05.XX.08.23.00	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_Aug2023.iso	12,467,961,856 bytes	English	-	OptiPlex 3000 Thin Client	1.11.0

Table 42. Build details of Dell Application Store

DAS installer version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)
23.08.0.4	23.08.0.4	DellApplicationStore_23.08.0.4.exe	10,94,24,056 bytes

BIOS is not part of this build. The above BIOS version is used during the build validation.

Windows 10 IoT Enterprise LTSC 2021

10.05.XX.10.22.00

Release summary

This release note contains information about the Windows 10 IoT Enterprise LTSC 2021 that runs on the OptiPlex 3000 Thin Client. Windows 10 IoT Enterprise LTSC 2021 is factory installed on the OptiPlex 3000 Thin Client. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager. The Windows 10 IoT Enterprise LTSC 2021 supports English and MUI languages.

Version

10.05.XX.10.22.00

Release date

October 2022

New and enhanced features

This release consists of two parts: the Dell Application Store and the e-support image.

- Dell Application Store
 - Dell Application Store is separate from the e-support image on [Dell Support](#) page. You must download the latest Dell Application Store from [Dell Support](#) page to get the following enhancements.
 - Unified Write Filter Servicing Mode: Servicing mode commands to service the device and apply Windows updates to the device.
 - A task scheduler "WindowsUWFServicing" (by default disabled) is created and set to trigger the servicing mode as required.
 - IT administrators can enable and schedule it as per their convenient maintenance time for the updates.
 - See [Important Notes](#) to know about the prerequisites for UWF Servicing Mode.
 - See [Apply Windows updates to UWF-protected devices | Microsoft Learn](#) for more information.
 - Included VMware Horizon Client 2206 and validated with the VMware Horizon Cloud Service.
 - VMware Horizon Cloud Services has been validated and is supported on Windows 10 IoT Enterprise LTSC 2021.
 - See [VMware Horizon Documentation - Horizon 8, Horizon Cloud Service, and Horizon Clients](#) for more information.
 - Latest third-party applications—See [Third-party & Dell value-added applications in Dell Application Store](#) for more information
 - Enabled Citrix Workspace App Current Release Version, replacing Citrix Workspace App LTSR (Long term service release) version
 - See [FAQ: Citrix Virtual Apps and Desktops and Citrix Hypervisor Long Term Service Release \(LTSR\)](#) to know more about the difference between CWA Current Release and CWA Long Term Service Release.
 - See [About this release | Citrix Workspace app for Windows](#) to know about the CWA 2209 Current Release.
 - Removed Citrix HDX Real Time Media Engine plug-in due to product EOML.
 - [Windows 10 IoT Enterprise LTSC 2021 for OptiPlex 3000 Thin Client Administrator's Guide](#) is updated with the notes to remove TightVNC (Virtual Network Computing) application.
 - E-support image

- The e-support image is updated to include the latest security intelligence updates for Microsoft Defender Antivirus and other Microsoft antimalware updates. See [QFEs list](#) for more information.
- As part of Dell Thin Client Application revamp, e-support image is included with latest Dell Application Control Center for better user experience. The inclusion of Dell Application Control Center in e-support image provides a better unified experience of Application Launch Manager, xData Cleanup Manager, Wyse Easy Setup, Wyse Device Agent and Custom Imaging scenarios when customers reimagine their devices with the latest e-support image. With this quarterly release, the functionalities of the Dell Thin Client Application are merged into the Dell Application Control Center. Also, the Dell Thin Client Application is removed from the e-support image.

(i) NOTE: If IT administrators do not plan to reload the e-support image, they can also download the security patches from [Microsoft Update Catalog](#) and follow the [Deployment Guide](#) for deployment. It can save time in deployment, image customization, and network traffic.

Important notes

UWF Servicing Mode and Task Scheduler Information

- Install July 12, [2022-KB5015807](#) as a pre-requisite QFE to function UWF Servicing mode.
- 'WindowsUWFServicing' is the scheduled task which is added and disabled by default to run at 3:00AM every Sunday every 4 Weeks for automatic windows updates.
- IT administrator can enable and update the scheduled timing as per their convenience.
- For UWF Servicing Mode, the device needs to be able to connect the Windows Updates servers.

Post Installing Dell Application Store

- After running the Dell Application Store, the Unified Write Filter tray user interface will be managed by Dell Application Control Center.
 - Right click and run as admin when starting Dell Application Control Center to continue to manage Unified Write Filter.
- (i) NOTE:** If you are using the latest 10.05.XX.10.22.00 e-support image, then Dell Thin Client Application is removed. Instead, Dell Application Control Centre is added as part of the e-support image for device configuration and management.

Dell Application Store- Citrix installation pre-requisite

- Citrix Workspace Application 22.9.0.28 requires Internet to install Microsoft Edge WebView2 Runtime as part of its installation through Dell Application Store.
- Alternative-
 - Users can Download [Microsoft Edge WebView2 Runtime](#) manually on thin client and install it.
 - Then install Citrix Workspace Application 22.9.0.28 from Dell Application Store 22.10.0.5, and then Citrix Workspace Application will be upgraded to 22.9.0.28 as expected.

QFEs list

Table 43. QFEs list

KB Number	Update Description
KB5013624	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5003791	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5015807	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5014032	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5014671	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5005699	Security Update for Windows 10 IoT Enterprise LTSC 2021

Third-party and Dell value-added applications in Dell Application Store

Table 44. Third-party applications

Application name	Version
Citrix Workspace App	22.9.0.28
VMware Horizon Client	8.6.0.29364 (2206)
TightVNC (Virtual Network Computing)	2.8.68.0
Zoom Plugins for Citrix and VMware	5.11.21750
Cisco Webex VDI (Virtual Desktop Infrastructure) Plugin	42.8.0.23281
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.1.0.56686
Cisco WebEx VDI ((Virtual Desktop Infrastructure) Meetings Plugin	42.2.6.11
Amazon WorkSpaces	5.1.0.3029

Table 45. Dell value-added applications

Application name	Version
Dell Secure Client	1.0.0.240
Wyse Easy Setup	2.0.0.320
Dell Application Control Center (DACC)	1.1.0.16
Application Launch Manager (ALM)	1.1.0.5
Dell Overlay Optimizer	1.0.1.53
Language Configuration Tool	1.0.0.10
xData CleanUp Manager (xDCM)	1.0.0.5
Quick Start	Not Applicable
Wyse Device Agent	14.6.6.3

Dell value-added applications/ Driver components

Table 46. Dell value-added applications driver details

Drivers/ Files	OptiPlex 3000 Thin Client
CAD-MAP-VDI	3.0.6.0

Table 47. Common application, features, and files- part of e-support image build 10.05.XX.10.22.00

Application	Version
Wyse Device Application (WDA)	14.6.6.3
PlatVsys	1.0.0.5
VMWare Horizon Client	8.4.0.24146
Merlin	4.1.0
Wyse Easy Setup	2.0.0.320
Application Launch Manager (ALM)	1.1.0.5

**Table 47. Common application, features, and files- part of e-support image build
10.05.XX.10.22.00 (continued)**

Application	Version
xData CleanUp Manager (xDCM)	1.0.0.5
Dell Command Monitor (DCM)	10.6.0.150
Citrix Workspace 1912	19.12.6000.9
Control Alt Del Map (CAD Map)	3.0.6.0
Microsoft Endpoint Configuration Manager	5.00.8790.1007
Build Content	1.0.0.8
Language Configuration Tool	1.0.0.9
Dell Application Control Centre	1.1.0.16
Custom Sysprep (Master.exe)	1.0.0.17
Azure Virtual Desktop	1.2.3401.0
Microsoft Edge Browser	103.0.1264.77
Quick Start	Not Applicable
Microsoft Remote Desktop Connection	10.0.19041 (Protocol 10.8 Supported)
TightVNC (Virtual Network Computing)	2.8.63.0

 **NOTE:** Factory image version number will change based on the production month and the year.

Test Environment

Table 48. Test Environment

Hardware Type	Hardware Rev	Model Name	CPU Name	Build Package Name	Product Version	RAM	SSD Size	BIOS Version
OptiPlex 3000 Thin Client	0502	OptiPlex 3000 Thin Client	Pentium	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_July2022.exe	10.05.09.07.22.00	8/16 GB	256 GB	1.5.0
OptiPlex 3000 Thin Client	0503	OptiPlex 3000 Thin Client	Celeron	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_July2022.exe	10.05.10.07.22.00	8/16 GB	256 GB	1.5.0

Compatibility

Build details

Table 49. General build details

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent version	Merlin USB Imaging Tool	MD5 File Checksum
OptiPlex 3000 Thin Client	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_Oct 2022.exe	10.0	10.05.XX.10.22.00	English	4.1.0	3.5.0.210	6419E733ED851C192DEA9CBA3822AC3D

Table 50. Platform specific build details of Wyse Management Suite

Platform(s)	Version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	Localization	BIOS Details	Platform	BIOS Version
OptiPlex 3000 Thin Client	10.0	10.05.XX.10.22.00	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_Oct 2022.exe	10,079,772,598 bytes	English	-	OptiPlex 3000 Thin Client	1.5.0

Table 51. Build details of Dell Application Store

DAS installer version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	MD5 File Checksum
22.10.0.5	22.10.0.5	DellApplicationStore_22.10.0.5.exe	1,496,748,784 bytes	F9076C9914425EB1D37EFCB91BB258AB

BIOS is not part of this build. The above BIOS version is used during the build validation.

Windows 10 IoT Enterprise LTSC 2021

10.05.XX.07.22.00

Release summary

This release note contains information about the Windows 10 IoT Enterprise LTSC 2021 that runs on the OptiPlex 3000 Thin Client. Windows 10 IoT Enterprise LTSC 2021 is factory installed on the OptiPlex 3000 Thin Client. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager. The Windows 10 IoT Enterprise LTSC 2021 supports English and MUI languages.

Version

10.05.XX.07.22.00

Release date

July 2022

New and enhanced features

This release consists of two parts: the Dell Application Store and the E-support image.

- Dell Application Store
 - Dell Application Store is separate from the e-support image on [Dell Support](#) page. Customers need to download the latest Dell Application Store from [Dell Support](#) page to get the following enhancements.
 - Auto Windows Defender Update allows users to automatically update the Windows Defender signature every day with Unified Write Filter ON.
 - Easy Setup in kiosk mode: New setting is available to set 12/24-time clocks from the thin client.
 - Latest third-party applications.
 - Refer to [Third-party & Dell value-added applications in Dell Application Store](#) for more information.
 - Optimization of memory utilization by removing RAM Disk after installing Dell Application Store.
 - Supports Microsoft Azure Virtual Desktop with latest exclusions, added as part of the Unified Write Filter.
- E-support image
 - The e-support image is updated to include the latest security intelligence updates for Microsoft Defender Antivirus and other Microsoft antimalware updates. Refer to [QFEs list](#) for more information.

(i) NOTE: If IT administrators do not plan to reload the e-support image, they can also download the security patches from [Microsoft Update Catalog](#) and follow the Security Patches Deployment Guide for deployment. It can save time in deployment, image customization, and network traffic.

Refer to [Important Notes](#) for more information on new and enhanced features.

Important notes

Citrix Desktop Viewer

- Citrix Desktop Viewer
 - The Citrix Desktop Viewer tool is made available on the connection so that customer can resize session without recourse to using shortcut keys as mentioned steps below:
 - Pass toolbar as a parameter from the UI and add it to the JSON file, instead of using API and shortcut keys. JSON will get replicated to the VDI session.
 - Edit the WebInterface.conf file in the locations given in the next two steps.
 - Open the C:\Inetpub\wwwroot\Citrix\XenApp\conf folder for Web Interface connections.
 - Open the C:\Inetpub\wwwroot\Citrix\PNAgent\conf folder for PNAgent connections.
 - Update the configuration file to remove the '#' and set ShowDesktopViewer=On.
 - The toolbar option will be displayed in the VDI session.

Post Installing Dell Application Store

- After running the Dell Application Store, the Unified Write Filter tray user interface will be managed by Dell Application Control Center.
- Right click and run as admin when starting Dell Application Control Center to continue to manage Unified Write Filter.

Task scheduler information to support Windows Defender Auto Updates

- 'WindowsDefenderUpdate' is the scheduled task which is added and enabled by default to run at 2:00AM every day for automatic updates of Defender signatures.
- Users can update the scheduled timing as per their convenience.
- To support the auto update, below exclusions are added Unified Write Filter.
 - HKLM\SOFTWARE\Microsoft\Windows NT\CurrentVersion\Schedule\TasksCache\Tasks
 - HKLM\SOFTWARE\Microsoft\Windows NT\CurrentVersion\Schedule\TasksCache\Tree

Dell Application Store- Citrix installation pre-requisite

- Citrix Workspace Application 22.3.1.41 requires internet to install Microsoft Edge WebView2 Runtime as part of its installation through Dell Application Store.
- Alternative-
 - Users can Download [Microsoft Edge WebView2 Runtime](#) manually on thin client and install it.
 - Then install Citrix Workspace Application 22.3.1.41 from Dell Application Store 22.07.0.5, and then Citrix Workspace Application will be upgraded to 22.3.1.41 as expected.

QFEs list

Table 52. QFEs list

KB Number	Update Description
KB5013624	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5003791	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5013942	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5014032	Security Update for Windows 10 IoT Enterprise LTSC 2021
KB5005699	Security Update for Windows 10 IoT Enterprise LTSC 2021

Third-party & Dell value-added applications in Dell Application Store

Table 53. Third-party applications

Application name	Version
Citrix Workspace App	22.3.1.41
Citrix HDX RealTime Media Engine	2.9.500.2802
VMware Horizon Client	8.5.0.26981
TightVNC (Virtual Network Computing)	2.8.68.0
Zoom Plugins for Citrix and VMware	5.11.21410
Cisco WebEx VDI (Virtual Desktop Infrastructure) Plugin	42.6.0.22645
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.1.0.56686
Cisco WebEx VDI ((Virtual Desktop Infrastructure) Meetings Plugin	42.2.6.11
Amazon WorkSpaces	5.0.0.2559

Table 54. Dell value-added applications

Application name	Version
Dell Secure Client	1.0.0.240
Wyse Easy Setup	2.0.0.241
Dell Application Control Center (DACC)	1.1.0.10
Application Launch Manager (ALM)	1.1.0.4
Dell Overlay Optimizer	1.0.1.53
Language Configuration Tool	1.0.0.10
xData CleanUp Manager (xDCM)	1.0.0.4
Quick Start	Not Applicable
Wyse Device Agent	14.6.4.8

Dell value-added applications/ Driver components

Table 55. Dell value-added applications driver details

Drivers/ Files	OptiPlex 3000 Thin Client
CAD-MAP-VDI	3.0.6.0

Table 56. Common application, features, and files- part of e-support image build 10.05.XX.07.22.00

Application	Version
Wyse Device Application (WDA)	14.6.3.1
PlatVsys	1.0.0.5
VMWare Horizon Client	8.4.0.24146
Merlin	4.1.0
Wyse Easy Setup	2.0.0.217

Table 56. Common application, features, and files- part of e-support image build 10.05.XX.07.22.00 (continued)

Application	Version
Application Launch Manager (ALM)	1.1.0.3
xData CleanUp Manager (xDCM)	1.0.0.3
Dell Command Monitor (DCM)	10.6.0.150
Citrix Workspace 1912	19.12.6000.9
Citrix HDX Real Time Media Engine (RTME)	2.9.400.2702
Control Alt Del Map (CAD Map)	3.0.6.0
Microsoft Endpoint Configuration Manager	5.00.8790.1007
Build Content	1.0.0.8
Language Configuration Tool	1.0.0.9
Dell Thin Client Application	10.0.0.27
Custom Sysprep (Master.exe)	1.0.0.17
Azure Virtual Desktop	1.2.3130.0
Microsoft Edge Browser	101.0.1210.53
Quick Start	Not Applicable
Microsoft Remote Desktop Connection	10.0.19041 (Protocol 10.8 Supported)
TightVNC (Virtual Network Computing)	2.8.63.0

 **NOTE:** Factory image version number will change based on the production month and the year.

Test Environment

Table 57. Test Environment

Hardware Type	Hardware Rev	Model Name	CPU Name	Build Package Name	Product Version	RAM	SSD Size	BIOS Version
OptiPlex 3000 Thin Client	0502	OptiPlex 3000 Thin Client	Pentium	Windows 10 IoT Enterprise LTSC 2021	10.05.XX.07.22. 00	8/16 GB	256 GB	1.0.2
OptiPlex 3000 Thin Client	0503	OptiPlex 3000 Thin Client	Celeron	Windows 10 IoT Enterprise LTSC 2021	10.05.XX.07.22. 00	8/16 GB	256 GB	1.0.2

Compatibility

Build details

Table 58. General build details

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent version	Merlin USB Imaging Tool
OptiPlex 3000 Thin Client	Windows10_IoT_Enterprise_LT SC_2021_OptiPI	10.0	10.05.XX.07.22. 00	English	4.1.0	3.5.0.210

Table 58. General build details

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent version	Merlin USB Imaging Tool
	ex_3000_July2022.exe					

Table 59. Platform specific build details of Wyse Management Suite

Platform(s)	Version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	Localization	BIOS Details	Platform	BIOS Version
OptiPlex 3000 Thin Client	10.0	10.05.XX.07.22.00	Windows10_IoT_Enterprise_LTSC_2021_OptiPlex_3000_July2022.exe	9,924,906,834 bytes	English	-	OptiPlex 3000 Thin Client	1.0.2

Table 60. Build details of Dell Application Store

DAS installer version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)
22.07.0.5	22.07.0.5	DellApplicationStore_22.07.0.5.exe	1252996528 bytes

BIOS is not part of this build. The above BIOS version is used during the build validation.

Windows 10 IoT Enterprise LTSC 2021

10.05.XX.06.23.00

Release summary

This release note contains information about the Windows 10 IoT Enterprise LTSC 2021 that runs on the OptiPlex 7410 All in One and Latitude 3440 Client. Windows 10 IoT Enterprise LTSC 2021 is factory installed on the OptiPlex 7410 All in One and Latitude 3440 Client. It provides the flexibility to be managed with Wyse Management Suite and Microsoft Endpoint Configuration Manager. The Windows 10 IoT Enterprise LTSC 2021 supports English and MUI languages.

Version

10.05.XX.06.23.00

Release date

July 2023

New and enhanced features

The following are all the new features delivered in this release.

- Supports OptiPlex 7410 All in One and Latitude 3440 Client Thin Client platform.
- Supports new Windows 10 IoT Enterprise LTSC 2021 Operating System.
- Supports Microsoft Azure Virtual Desktop.
- Supports H.265 codec with HEVC.
- Supports latest Microsoft Edge Chromium Browser.
- Enhanced the Wyse Easy Setup support for newer Microsoft Edge Browser configurations and Microsoft Azure Virtual Desktop feature. This is provided as a custom application additional support.
- Supports Wyse Management Suite/ USB image deployment-Secure boot.
- Support of ISO format on Imaging support from Wyse Management Suite and Dell OS recovery tool.

Compatibility

Build details

Table 61. General build details

Platform(s)	Product	Build Version	Build Number	Localization	Boot Agent version
OptiPlex 7410 All in One and Latitude 3440 Client	WinIoT_LTSC_2021_Latitude_3440_June2023.ISO WinIoT_LTSC_2021_OptiPlex_7410_June2023.ISO	10.0	10.05.XX.06.23.00	English	4.3.0

Table 62. Platform specific build details of Wyse Management Suite

Platform(s)	Version	Build Number	Build Wyse Management Suite Package Name	Build Size (Bytes)	Localization	BIOS Details	Platform	BIOS Version
OptiPlex 7410 All in One and Latitude 3440 Client	10.0	10.05.XX.06.23.00	WinIoT_LTS_C_2021_OptiPlex_7410_June2023.ISO WinIoT_LTS_C_2021_Latitude_3440_June2023.ISO	12,064,256	English	-	OptiPlex 7410 All in One Latitude 3440 Client	1.5.1

BIOS is not part of this build. The above BIOS version is used during the build validation.

Third-party applications in Dell Application Store

Table 63. Third-party applications

Application name	Version
Citrix Workspace App	19.12.6000.9
Citrix HDX Realtime Media Engine	2.9.400.2702
VMware Horizon Client	8.4.0.24146
TightVNC (Virtual Network Computing)	2.8.63.0
Zoom Plugins for Citrix and VMware	5.9.20742
Cisco WebEx VDI (Virtual Desktop Infrastructure) Plugin	41.12.0.20899
Cisco Jabber Softphone for VDI (Virtual Desktop Infrastructure) Client	14.0.1.55989
Cisco WebEx VDI ((Virtual Desktop Infrastructure) Meetings Plugin	41.4.7.10
Amazon WorkSpaces	4.0.6.2415

Table 64. Dell value-added applications

Application name	Version
Dell Secure Client	1.0.0.240
Wyse Easy Setup	2.0.0.241
Dell Application Control Center (DACC)	1.1.0.10

Hardware support information

- OptiPlex 7410 All in One—8/16/32 GB RAM, 256 GB SSD.
- Latitude 3440 Client—8/16/32 GB RAM, 256 GB SSD.

Table 65. Supported displays

Hardware	Operating System	Single Display (in built)	Dual Display
OptiPlex 7410 All in One and Latitude 3440 Client	Windows 10 IoT Enterprise LTSC 2021	Supported	Supported

Supported languages

- English (en-US)
- German (de-DE)
- French France (fr-FR)
- French Canada (fr-CA)
- Italian (it-IT)
- Spanish (es-ES)
- Japanese (ja-JP)
- Korean (ko-KR)
- Chinese Simplified (zh-CN)
- Chinese traditional (zh-TW)
- Brazilian Portuguese (pt-BR)
- Dutch Netherlands (nl-NL)
- Danish Denmark (da-DK)
- Finnish Finland (fi-FI)
- Norwegian Norway (nb-NO)
- Russian Russia (ru-RU)
- Swedish Sweden (sv-SE)

Important notes

Test Environment

Table 66. Test Environment

Hardware Type	Model Name	CPU Name	Build Package Name	Product Version	RAM	SSD Size	BIOS Version
OptiPlex 7410 All in One	OptiPlex 7410 All in One	Pentium, Celeron, Intel i3, Intel i5	Windows 10 IoT Enterprise LTSC 2021	10.05.XX.06.23.00	8/16/32 GB	256 GB	1.5.1
Latitude 3440 Client	Latitude 3440 Client	Pentium, Celeron, Intel i3, Intel i5	Windows 10 IoT Enterprise LTSC 2021	10.05.XX.06.23.00	8/16/32 GB	256 GB	1.5.1

4K monitors

The OptiPlex 3000 Thin Client supports Dell U3223QE, U2723QE, U3219Q 4K, and 4323QE monitors.

Non 4K monitors

Table 67. Non 4K monitors

Number of displays	Monitors
One display	U2422HE
	P2422HE
	P2722HE
	U2722D
	C2722DE

Table 67. Non 4K monitors (continued)

Number of displays	Monitors
	P2722H
	P2222H
	P2421
	P2421D
	P2720D
	P2720DC
	U2520D
	U3421WE
	U3423WE
	E1920H
	E2420H
	E2720H
	E2720HS
	P2319H
	P2418HT
	U3023E
Two displays	P2422H
	U2422H
	C2422HE
	C2722DE
	E2020H
	U3821DW
	P3421W
	C3422WE
	U3423WE

Used space and free space

Table 68. Used space and free space

Platform	SSD	Used space	Free space
OptiPlex 7410 All in One	256 GB SSD	14GB	219GB
Latitude 3440 Client	256 GB SSD	16GB	217GB

QFEs list

Table 69. QFEs list

KB Number	Update Description
KB5003791	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021

Table 69. QFEs list (continued)

KB Number	Update Description
KB5005699	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5022502	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5012170	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5026361	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5014032	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021
KB5025315	Update for Microsoft Windows 10 IoT Enterprise LTSC 2021

Operating system/ Driver components

Table 70. Driver details

Drivers/ Files	OptiPlex 3000 Thin Client
CAD-MAP-VDI	3.0.6.0

Table 71. Common application, features, and files- part of e-support image build 10.05.XX.06.23.00

Application	Version
Wyse Device Application (WDA)	14.6.9.21
PlatVsys	1.0.0.6
VMWare Horizon Client	8.8.0.33776
Merlin	4.1.3
Wyse Easy Setup	2.0.0.471
Application Launch Manager (ALM)	1.1.0.10
xData CleanUp Manager (xDCM)	1.0.0.8
Dell Command Monitor (DCM)	10.9.0.307
Citrix Workspace 1912	23.3.0.55
Control Alt Del Map (CAD Map)	3.0.6.0
Microsoft Endpoint Configuration Manager	5.00.8790.1001(2019)
Build Content	1.0.0.8
Language Configuration Tool	1.0.0.10
Application Control Center	1.1.0.33
Custom Sysprep (Master.exe)	Not Applicable
Azure Virtual Desktop	1.2.4240.0
Microsoft Edge Browser	113.0.1774.57
Microsoft Remote Desktop Connection	10.0.19041 (Protocol 10.8 Supported)
TightVNC (Virtual Network Computing)	2.8.75.0

(i) NOTE: Factory image version number will change based on the production month and the year.

Peripherals ecosystem

Table 72. Peripherals ecosystem

Product Category (Module)	Product Description
Monitors	Dell 27 USB-C HUB Monitor - P2723DE - P2723DE Dell 22 Monitor - P2222H - P2222H Dell 24 Monitor - P2421 - P2421 - P2421 Dell 24 Monitor - P2421D - P2421D - P2421D Dell 24 Monitor - P2423 - P2423 Dell 24 USB-C Hub Monitor - P2422HE - P2422HE Dell UltraSharp 24 Monitor - U2422H - U2422H
Audio	Dell Pro Wireless Headset - Daybreak - WL5022 Dell Slim Conferencing Soundbar - Lizzo - SB522A Dell Speakerphone - Mozart - SP3022 Dell Stereo Headset - Presto - WH1022
Input Devices	Dell Pro Wireless Keyboard and Mouse - Tasman (previous Windsor) - KM5221W Dell Active Pen - Pandora - PN5122W Dell Pro Wireless Keyboard and Mouse - Tasman (previous Windsor) - KM5221W Dell Full-Size Wireless Mouse - Daintree - MS300 Dell Mobile Pro Wireless Mice - MS5120W_Black - Splinter - MS5120W Dell Multi-Device Wireless Keyboard - Corbett - KB700 Dell Multi-Device Wireless Keyboard and Mouse Combo - KM7120W - KM7120W - Felix Dell Multi-Device Wireless Mouse - MS5320W - MS5320W - Comet Dell Multimedia Keyboard - KB216_BLACK - KB216 - KB216 - Rusty Dell Optical Mouse - MS116_BLACK - MS116 - MS116 - Sapphire Dell Palm Rest for KB216 and KM636 - PR216 - PR216 Dell Premier Multi-Device Wireless Keyboard and Mouse - Acadia IO - KM7321W Dell Pro Wireless Keyboard and Mouse - Tasman (previous Windsor) - KM5221W Dell Active Pen - Pandora - PN5122W
Cables, Dongles, Adapters	Dell 7-in-1 USB-C Multiport Adapter - Slayer 3 MLK - DA310 100W Adapter Type-C AC adapter - Miami Beach 100W - NA
Webcam	Dell Pro Webcam - Falcon - WB5023
Docks & Port Replicators	Dell USB-C Dock - WD19S 130W - Salomon S - WD19S 130W

Boot sequence

- The first boot is Windows Boot Manager.
- The second boot is Merlin Non-Pxe.
- The third boot is UEFI HTTPs Boot.
- The fourth boot is UEFI CL1-3D256-Q11 NVMe SSTC 256 GB TWOTN2CC9DH000BB09161.
- The fifth boot is ONBOARD NIC (IPV4).
- The sixth boot is ONBOARD NIC (IPV6).

Resources and support

Accessing documents using the product search

1. Go to www.dell.com/support.
2. In the **Enter a Service Tag, Serial Number, Service Request, Model, or Keyword** search box, type the product name. For example, **OptiPlex 7410 All-In-One** or **Latitude 3440 Client**. A list of matching products is displayed.
3. Select your product.
4. Click **Documentation**.

Accessing documents using product selector

You can also access documents by selecting your product.

1. Go to www.dell.com/support.
2. Click **Browse all products**.
3. Click **Computers**.
4. Click **Thin Clients**.
5. Click **OptiPlex Thin Client**.
6. Click **OptiPlex 7410 All-In-One** or **Latitude 3440 Client**.
7. Click **Select this Product**.
8. Click **Documentation**.

Contacting Dell

About this task

 **NOTE:** If you do not have an active Internet connection, you can find contact information from your purchase invoice, packing slip, bill, or Dell product catalog.

Dell provides several online and telephone-based support and service options. Availability varies by country/region or region and product, and some services may not be available in your area. To contact Dell for sales, technical support, or customer service issues:

Steps

1. Go to www.dell.com/support.
2. Select your support category.
3. Verify your country/region or region in the **Choose a Country/Region** drop-down list at the bottom of the page.
4. Select the appropriate service or support link that is based on your need.