


Slot Adapter Removal Instructions



Step 1

Apply a generous amount of adhesive remover around the slot adapter ensuring not to get the solution onto any sensitive components or areas of the device.




Step 2

Let adhesive remover solution sit for 12-24 hours.



Step 3

Use a thin and flexible plastic, such as a gift card or pan scraper, to wedge between the adhesive slot and the device surface until it is freed.



Step 4

Use a damp cloth to wipe away any remaining residue and solutions.