

MPN: MSP311039

Fuser Fixing Film W/O Syringe of Grease) for HP LaserJet Enterprise M607dn/607n, LaserJet Enterprise M608dn/608n/608x, LaserJet Enterprise M609dh/609dn/609x, LaserJet Enterprise MFP M631dn, LaserJet Enterprise MFP 631z, LaserJet Enterprise MFP 632fht, LaserJet Enterprise MFP 632h, LaserJet Enterprise MFP 633fh, LaserJet Enterprise Flow MFP M631h, LaserJet Enterprise Flow MFP 632z, LaserJet Enterprise Flow MFP 633z, LaserJet Enterprise M610dn/611dn/611x/612dn/612x

Extend the life of your Printers and Copiers. CoreParts offers a wide range of internal parts for printer and Copier, for all major Printer brands that matches the performance of the originals.

- High Quality
- Tested and certified
- Matching Performance
- Reliable with 12 month Warranty



Specifications

Vendor information	Brand Name	CoreParts
	Warranty	1 Year(s)