

























Lirio
by
PHILIPS

CE Distributor
Satenrozen 13
2550Kontich — Belgium
PC MD0 001 973
A346 Last update: 10/08/09










CREATE **LIGHT CONTROL** **SHADOW**






CREATE **LIGHT** CONTROL **SHADOW**





CREATE **LIGHT** CONTROL **SHADOW**



Nederlands

Binnen sommige elektromagnetische storingen kan de touchdimmer zijn dimfunctie verliezen. Na de storingen zal de dimmer zijn functie automatisch zelfstandig herstellen.

Français

En cas d'interférences électromagnétiques, le variateur sensible peut perdre de son efficacité. Cette fonction se rétablit automatiquement dès la disparition de ces interférences.

English

The touch dimmer may lose its dimming function within some frequencies of electromagnetic disturbances. The touch dimmer is able to restore its function automatically after the electromagnetic disturbances disappear.

Deutsch

Durch das auftreten von elektromagnetischen Störungen in bestimmten Frequenzen könnte der Touchdimmer gegebenenfalls seine Funktion verlieren.